

Ships Detained in Hong Kong Due to PSC Inspection in September 2023

No.	IMO No.	Ship Name	Flag	Date of Keel Laid	GRT	Ship Type	Classification society	Related ROs	Company	Date of Detention	Date of Release	Nature of Detainable Deficiencies (responsible RO, if any)
1	9165059	RUI HAI 2	Palau	14.05.1997	6870	General cargo/multipurpose	International Register of Shipping	International Register of Shipping	RUI HAI INTERNATIONAL SHIPPING CO., LIMITED	13.09.2023	19.10.2023	1. Both STBD & PORT Lifeboat cannot perform steering by the helm, the batteries selection switches are not arranged in order for engine starting. The 'markings on exterior' is not marked in order as per statutory requirement (such as the Ship and Port name was not marked at designated location (Bow)); 2. Engine Room Ventilator Dampers (located at main deck) are not operative; 3. The Remote Control ('Emergency Stop Switch') for engine room fuel pumps and related equipments is not operative. No indications to list out the corresponding service zones / equipments; and 4. The implementation of ship's ISM failed to ensure proper maintenance of the ship with objective evidence of above deficiency items.
2	8532372	STAR JANET	Tanzania	08.01.2004	499	General cargo/multipurpose	Eagle Classification of Shipping	Eagle Classification of Shipping	HONG-LI COMPANY LIMITED	18.09.2023	-	1. There was no medical certificates for all crew members onboard; 2. All crew members had not been paid wage for July and August 2023; 3. Second officer, second engineer and two ABs had not COC, COP and all crew members had not flag state's endorsement; 4. All fire fighting equipment service report was no available, fire fighting equipment expired; 5. Fire drill was conducted unsatisfactory, crew were not familiar with the fire drill; 6. No record of fire alarm system test and fire detection system was not working; 7. Fire pump / emergency fire pump not working; 8. Port and starboard Life-raft was not secured properly and life saving appliance service report was no available; 9. Test several valves on fire main line and found inoperational; 10. No.2 auxiliary generator engine was not working; and 11. Emergency escape was kept open and was obstructed electric wire.
3	8746789	FIVE STAR	Sierra Leone	30.01.2008	2911	General cargo/multipurpose	Asia Shipping Certification Services (ASCS)	Asia Shipping Certification Services (ASCS)	Shanghai Debei Shipping Co.,Ltd	21.09.2023	27.09.2023	1. Emergency escape door in the engine room cannot self-close properly; 2. Several fire doors including the entry of E/R self-closing device failure; 3. Remote control (stop) for power ventilation of machinery space is not operable; 4. Remote control (stop) for oil transfer equipment cannot demonstrate to be operable during inspection; 5. Fire drill was conducted and found not satisfactory as crew do not familiarize their duty and donning the fireman outfits; and 6. Two outstanding deficiencies were found not rectified before the due date and implementation of the ISM was found failure during the inspection. (PSC inspection dated 19.07.2023 and 15.05.2023)