

## Ships detained in Hong Kong by PSC Section in October 2011

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	8810401	FEN JIN 2	Panama	1989	2561	Others	Panama Maritime Documentation Services	Panama Maritime Documentation Services; Panama Bureau of Shipping	Ocean Grow International Shipmanagement Consultant Corp.	10/10/11	17/10/11	FIRE SAFETY MEASURES: doors within main vertical zone, boat deck stairway, fire doors missing, doors within main vertical zone, bridge deck, self-close device out of order, fire door difficult to close, personal equipment, fireman's outfit on bridge, not ready for use (stored with other items), flashlight not working, readily availability of fire fighting equipment, s'side fire main isolation valve seriously leaking, readily availability of fire fighting equipment, fire hose leaking seriously during testing; LIFESAVING APPLIANCES: lifebuoys, MOB lifebuoys on bridge wings, smoke signals not properly installed for free falling, SAFETY OF NAVIGATION: gyro compass, magnetic compass, about 160 degrees different from steering compass; MARPOL RELATED OPERATIONAL DEFICIENCIES: oil and oily mixtures from machinery spaces, excess amount of oily water accumulated in e/r floors; LOAD LINES: covers (hatchway-, portable-, tarpaulins, etc.), gasket rubber for hatch covers, part loose/missing & poor conditions, ventilators, air pipes, casings, TST 7S sounding pipe corroded/broken, doors, no. 1 cargo hold door open to fwd deck locker, blocked by wire/rope & could not be water-tighted
2	9433949	JACKELINE-H	Antigua and Barbuda	2008	7464	Container ship	Germanischer Lloyd	Germanischer Lloyd	Reederel hinsch gmbh and co. kg	11/10/11	12/10/11	LIFESAVING APPLIANCES: lifeboats, lifeboat engine failed to start even after spending more than 1.5 hours
3	9334208	TAI DE SHENG	Panama	2003	1948	General cargo/multi-purpose ship	Isthmus Bureau of Shipping	Isthmus Bureau of Shipping; Panama Bureau of Shipping	Ocean Grow International Shipmanagement Consultant Corp.	24/10/11	- - -	MOORING ARRANGEMENTS (ILO 147): anchoring devices, stbd side anchor lost; LOAD LINES: doors, 3 watertight doors heavily rusted & damaged; PROPULSION AND AUXILIARY MACHINERY: cleanliness of engine room, e/r very oily dirty; STABILITY, STRUCTURE AND RELATED EQUIPMENT: stability/strength/loading information and instruments, stability booklet is only in Chinese. (Master & c/o are myanmar, do not know Chinese); MARPOL - ANNEX V: garbage record book, c/o cannot present garbage record book; MARPOL - ANNEX I: oil record book, c/e cannot present oil record book, 15 ppm alarm arrangements, 15ppm alarm not work

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.