

Ships detained in Hong Kong by PSC Section in June 2013

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	8657536	FU HONG	Cambodia	2005	2986	General cargo/ multipurpose	Union Bureau of Shipping	Union Bureau of Shipping	Dahan (HK) Shipping Co Ltd	03/06/13	09/06/13	CERTIFICATE AND DOCUMENTATION: crew certificates/endorsement by flagstate/c/e and c/o's COC flag state endorsement or COR n/a, documents/oil record book/oil record book before 21/May/2013 n/a; SAFETY OF NAVIGATION: navigation bridge visibility/bridge visibility not meeting SOLAS requirements, front window inclination less than 10 degrees, only one clearview screen and not window wipers provided, ship's side not visible from wings; WATER/WEATHERTIGHT CONDITIONS: ventilators, air pipes, casings/anchor chain lockers exposed to forecandle store without watertight arrangement; FIRE SAFETY: remote means of control (opening, pumps, ventilation, etc.) machinery spaces/f.o. serv. tank remote shut-off inoperative, operation of fire protection systems/all officers not aware of operation of fixed CO ₂ fire extinguishing system; LIFE SAVING APPLIANCES: maintenance and inspections/lifeboats condition not maintained properly. both canopy lights unlit, viewing windows blurred, side grab lifeline broken
2	8107311	RAYNA	Comoros	1982	21551	Bulk carrier	Bularian Register of Shipping	- - -	Bulcom Ltd	04/06/13	04/07/13	SAFETY OF NAVIGATION: voyage data recorder (VDR)/simplified voyage data recorder(S-VDR)/VDR annual survey expired, VDR battery expired in Aug 2010, radar/S-Band radar not working properly, other (navigation)/bridge steering gear control system not working; POLLUTION PREVENTION - MARPOL ANNEX V: incinerator incl. operations and operating manual/incinerator not working; PROPULSION AND AUXILIARY MACHINERY: propulsion main engine/main engine remote control from engine control room out of order; RADIO COMMUNICATIONS: facilities for reception of marine safety inform./NAVTEX not working; FIRE SAFETY: fire detection and alarm system/bridge fire detector system not working; LIFE SAVING APPLIANCES: stowage and provision of lifeboats/port side lifeboat launching winch not working properly
3	8631702	YUN SHIN	Sierra Leone	1988	694	General cargo/ multipurpose	Dromon Bureau of Shipping	- - -	Billion Star Marine Services Ltd	11/06/13	14/06/13	SAFETY OF NAVIGATION: voyage or passage plan/passage plan not available; LIFE SAVING APPLIANCES: radio life-saving appliances/two-way VHF not available; FIRE SAFETY: personal equipment for fire safety/fire fighter's outfit, short of axe, safety line, safety lamp; POLLUTION PREVENTION - MARPOL ANNEX I: oil and oily mixtures from machinery spaces/e/r, tank top bilge water accumulated 80cm in depth; CERTIFICATE AND DOCUMENTATION - DOCUMENTS: oil record book/last bunkering operation not recorded in oil record book, bunkering delivery notes not available onboard

4	9012862	CONCORD	Indonesia	1992	12405	Container	Nippon Kaiji Kyokai	Nippon Kaiji Kyokai	Evergreen Marine Corp (Taiwan) Ltd (Evergreen Line)	19/06/13	21/06/13	LIFE SAVING APPLIANCES: lifeboats/portside lifeboat engine failed to start, lifeboats/holes at suspension hook-not be covered and ensure l/b watertight; CARGO OPERATIONS INCLUDING EQUIPMENT: cargo securing manual/cargo securing manual not found onboard; ISM : shipboard operations/referring to deficiencies item 1-18 of PSC inspection report, SMS was not properly implemented onboard, resources and personnel/key officer do not know emergency generator auto start test procedure and can not understand the procedure in chinese; RADIO COMMUNICATIONS: MF/HF radio installation/ac power failed to supply to GMDSS; FIRE SAFETY: fire fighting equipment and appliances/two fire hoses heavily leaking during testing, fire fighting equipment and appliances/fire hose can not connect to portbow fire hydrant; SAFETY OF NAVIGATION: charts/BA chart 1962 for last and intended voyage expired
5	8747874	SHUN HENG	Panama	1995	1720	Container	Overseas Marine Certification Services	Overseas Marine Certification Services	Sun Rising Shipmanagement Co Ltd	26/06/13	04/07/13	FIRE SAFETY: fire doors/openings in fire-resisting divisions/all fire doors in accommodation kept to open by extra rope or wire, some self-close devices not working; SAFETY OF NAVIGATION: nautical publications/sailing direction NP31, NP32 expired, charts/BA chart for last & intended voyage no. 937, 1962, 4121 expired; POLLUTION PREVENTION - MARPOL ANNEX I: oil and oily mixtures from machinery spaces/e/r, tank top oily water accumulated in depth of 45cm

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.