

Ships detained in Hong Kong by PSC Section in March 2011

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	9179476	SILVER OCEAN	Bahamas	1999	9030	Container	American Bureau of Shipping	American Bureau of Shipping; Germanischer Lloyd; Det Norske Veritas	Wallem Shipmanagement Ltd	01/03/11	04/03/11	ALARM SIGNALS: fire alarm, more than two fire detectors in e/r not working; MARPOL - ANNEX I: 15 ppm alarm arrangements, 15 ppm alarm is not working; FIRE SAFETY MEASURES: emergency fire pump, emergency fire pump is not working; SAFETY OF NAVIGATION: navigation bridge visibility, one wiper in wheelhouse is not working, nautical publications, ITU book and IAMSAR manual vol. 3 are out of date; PROPULSION AND AUXILIARY MACHINERY: cleanliness of engine room, e/r found serious oily and large amount of bilgewater in bottom of e/r.
2	8622335	DONG YI	Panama	1983	998	General cargo/multi-purpose ship	Isthmus Bureau of Shipping	Isthmus Bureau of Shipping	East Harbour Navigation Co Ltd	07/03/11	08/03/11	STABILITY, STRUCTURE AND RELATED EQUIPMENT: ballast, fuel and other tanks, fore end deep tank watertight door damaged, bulkheads - corrosion, fore end deep tank watertight bulkhead found damaged holes; LOAD LINES: doors, fore end watertight door on main deck cannot be closed, doors, watertight door from engine room to cargo hold cannot be closed
3	8504870	ADMIRAL T	Panama	1986	22607	Bulk carrier	Registro Italiano Navale	Registro Italiano Navale; Panama Register Corporation; Overseas Marine Certification Services	Nortech Shipping Ltd.	15/03/11	14/04/11	LIFESAVING APPLIANCES: lifeboats, engines of two lifeboats are not working, inflatable liferafts, one inflatable liferaft was missing; FIRE SAFETY MEASURES: fire detection, 5 smoke detectors of fire detecting systyem are not working; MARPOL - ANNEX I: 15 ppm alarm arrangements, oily water separator/15ppm alarm was not working; SAFETY OF NAVIGATION: navigation bridge visibility, wiper and one CVS are not working, echo-sounding device, echo sounder was not working; SHIP'S CERTIFICATES AND DOCUMENTS: other, ship certificates are not valid (SML, ITC, ILLC, CSSE, CSSC, CSSR, IOPP, IAPP, ISPP).

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.