

Ships detained in Hong Kong by PSC Section in April 2011

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	9007518	THERAPS	Liberia	1991	14867	Container ship	Germanischer Lloyd	Germanischer Lloyd	Multibulk Marine Management SA	29/04/11	14/05/11	FIRE SAFETY MEASURES: fire detection/smoke detectors and system in E/R found out of order, jacketed piping system for high pressure fuel lines/two high pressure f.o. pipes (for M/E) insulation and connection found damaged, jacketed piping system for high pressure fuel lines/many high pressure f.o. pipe for M/E found leaking oil; STABILITY, STRUCTURE AND RELATED EQUIPMENT: emergency lighting, batteries and switches/emergency generator not working properly (1. need 5 minutes to stop; 2. engine stop shortly after start; 3. battery charger gauge not working)

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.