

## Ships detained in Hong Kong by PSC Section in October 2012

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	9604653	SM AURORA	Panama	2011	44737	Bulk carrier	Korean Register of Shipping	Korean Register of Shipping; Bureau Veritas; Germanischer Lloyd	Eastern Media International Corp (EMIC)	04/10/12	05/10/12	EMERGENCY SYSTEMS: fire drills/fire drill (engine room fire) not satisfactory (E/R ventilation and fire damper not close, crew not familiar with their duty), emergency source of power - emergency generator/quickly close valve of diesel oil supply tank for emergency generator not work properly, hard to operation; SAFETY OF NAVIGATION: nautical publications/notices to mariners of 2012 not available onboard, charts/BA charts 3026/937/4127 for last and intend voyage not updated correction; POLLUTION PREVENTION - MARPOL ANNEX IV: sewage discharge connection/sewage directly discharge to sea; FIRE SAFETY: fixed fire extinguishing installation/key engineer did not know the operation of fixed CO <sub>2</sub> system alarm testing
2	7722827	TAJRI 1	Sierra Leone	1983	826	Oil tanker	International Register of Shipping	International Register of Shipping	Pt. Pelayaran Tajri Samudera	09/10/12	19/10/12	SAFETY OF NAVIGATION: radar/radar not working, nautical publications/BA charts for present voyage not up to date (1918), and lack of proper scale charts (1555, 3706, 3991, 3987, 3988), nautical publications/all nautical publications not available; FIRE SAFETY : fire pumps and its pipes/fire pump not produced sufficient water pressure, fire fighting equipment and appliances/fixed CO <sub>2</sub> system out of order, crew not know operation of it, fixed fire extinguishing installation/p'side main deck, fire main line no water delivery during testing, fixed fire extinguishing installation/s'side main deck, fire main line one hydrant valve missed, temporarily fixed by wooden plug, one hydrant valve leaking, ready availability of fire fighting equipment/fire hose leaking during testing, 6 pieces of nozzle shorted, ready availability of fire fighting equipment/numerous portable fire extinguisher expired & low pressure, personal equipment for fire safety/only one set of fire fighter's outfit onboard, without BA set; LIFE SAVING APPLIANCES: lifebuoys incl. provision and disposition/all lifebuoy aged broken, wrong ship's name marked, lifejackets incl. provision and disposition/numerous life jackets on self-ignition light and whistle; CERTIFICATE AND DOCUMENTATION: ship certificates/continuous synopsis record/CSR not available onbaord, documents/SOPEP/SOPEP not available onboard, documents/oil record book/oil record book not available onboard; EMERGENCY SYSTEMS: emergency source of power - emergency generator/emergency generator not working; ALARMS: fire alarm/bridge, fire alarm control system not working; POLLUTION PREVENTION - MARPOL ANNEX V: garbage management plan/garbage management plan and record book not available onboard

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.