

Ships detained in Hong Kong by PSC Section in May 2014

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	8654637	MIDLAND	Kiribati	2007	2909	General cargo/ multipurpose	International Ship Classification	International Ship Classification	Shanghai Huihai Ship Technology Co Ltd	12/05/14	15/05/14	LIFE SAVING APPLIANCES: maintenance and inspections/lifeboat release hook reset not in position as per instruction diagram; EMERGENCY SYSTEMS: emergency fire pump and its pipes/emergency fire pump starting by battery failed, emergency, lighting, batteries and switches/emergency battery 24V for w/h equipment found s.g. low (1.10-1.15); POLLUTION PREVENTION - MARPOL ANNEX I: oil filtering equipment/OWS alarm failed and spare part not available; ISM: company verification, review and evaluation/from the evidences of deficiencies in form b, the verification and evaluation of the implementation of shipboard SMS not effective, FIRE SAFETY: ventilation/e/r ventilator - starbd, seized and missing marking open.. shut
2	8630241	SHUN DA	Panama	1986	2363	Container	Overseas Marine Certification Services	Overseas Marine Certification Services	Sun Rising Shipmanagment Co Ltd	15/05/14	19/05/14	FIRE SAFETY: fire detection and alarm system/smoke detectors in e/r not working; SAFETY OF NAVIGATION: nautical publications/ITU book list of ship station missing; PROPULSION AND AUXILIARY MACHINERY: propulsion main engine/heat insulation on exhaust pipe of main engine found damaged, propulsion main engine/main engine casing was oily; LIVING AND WORKING CONDITIONS - WORKING CONDITIONS: safe means of access/many valves covers on e/r floor missing; CERTIFICATE AND DOCUMENTATION - DOCUMENTS: SOPEP/SOPEP and T&S booklet missing
3	9073311	XING YUAN	Cambodia	1993	3015	General cargo/ multipurpose	Union Bureau of Shipping	Union Bureau of Shipping	Yun Xing Shipping Co Ltd	20/05/14	24/05/14	SAFETY OF NAVIGATION: speed and distance indicator/speed log not working, ARPA indicates speed log sensor error; FIRE SAFETY: jacketed high pressure lines and oil leakage alarm/m/e jacketed high pressure fuel leakage alarm piping dismantled at all connections, causing alarm system not functioning, fixed fire extinguishing installation/fixed CO ₂ system for e/r and cargo holds, one section of starting CO ₂ pipe broken at connection, ten cylinders without starting arrangements, piping to cargo holds corroded seriously, operation manual
4	9158783	SHUN TAI 98	Panama	1997	4165	Container	Panama Shipping Registrar Inc.	Panama Shipping Registrar Inc.	Sun Rising Shipmanagment Co Ltd	22/05/14	23/05/14	SAFETY OF NAVIGATION: voyage or passage plan/voyage plan not properly prepared, no sufficient information to ensure safety of navigation, charts/intended voyage charts short of BA937, 1962, 3026; FIRE SAFETY: fire detection and alarm system/fire detection and alarm system zone 5 and zone 14 flailure; RADIO COMMUNICATIONS: MF/HF radio installation/MF/HF DSC radio no reserve power supply; LIFE SAVING APPLIANCES: lifebuoys incl. provision and disposition/pside bridge wing MOB lifebuoy mass less than 4kg, smokeand light signal expired

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.