

Ships detained in Hong Kong by PSC Section in July 2014

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	9092331	DONG PENG	Panama	1993	1064	General cargo/ multipurpose	Overseas Marine Certification Services	Overseas Marine Certification Services; Isthmus Bureau of Shipping, S.A.	East Harbour Navigation Co Ltd	09/07/14	11/07/14	WATER/WEATHERTIGHT CONDITIONS: covers (hatchway-, portable-, tarpaulins, etc.)/cargo hatch covers, rubber packing missing in several sections; LIFE SAVING APPLIANCES: launching arrangements for rescue boats/rescue boat launching davit seized and recovering winch motor not functional, causing launching failure; POLLUTION PREVENTION - MARPOL ANNEX IV/sewage treatment plant/sewage treating plant not working; FIRE SAFETY: other (fire safety)/D.O. service tank in e/r found persistent leakage
2	8748232	SHUN HONG	Panama	1993	2388	General cargo/ multipurpose	Overseas Marine Certification Services	Overseas Marine Certification Services; Panama Shipping Registrar Inc.	Yangning Marine International Co Ltd	14/07/14	16/07/14	CERTIFICATE AND DOCUMENTATION - CREW CERTIFICATES: certificate for medical care/ship master medical fitness certificate was outdated, chief engineer and one able seaman medical fitness certificates were missing on board; LIFE SAVING APPLIANCES: lifeboats/life boat engine was not working; LIVING AND WORKING CONDITIONS - WORKING CONDITIONS: safe means of access/many valves covers on engine room floor were missing; WATER/WEATHERTIGHT CONDITIONS: ventilators, air pipes, casings/one air pipe cover on port side main deck was damaged
3	9446893	DONG PENG 58	Cambodia	2003	4090	General cargo/ multipurpose	Union Bureau of Shipping	Union Bureau of Shipping	Haistar Maritime Co Ltd	16/07/14	21/07/14	POLLUTION PREVENTION - MARPOL ANNEX IV : sewage treatment plant/sewage treatment plant poor condition (e.g. transparent inspection pipe/port unable to check the system working/glass cracked, disinfection feed not functioned, etc.); POLLUTION PREVENTION - MARPOL ANNEX I : oil filtering equipment/oily water separator overboard discharge valve not functioned and unable to test the equipment; FIRE SAFETY: fire-dampers/e/r fire damper/ventilator (p& amp; s) and w/t door at funnel unable to close fully (abt 1 cm gaps), fire doors/openings in fire-resisting divisions/two fire doors from accommodation to e/r lashed open/self-closing device damaged; WATER/WEATHERTIGHT CONDITIONS: ventilators, air pipes, casings/fwt air pipe head missing
4	8631702	YUN SHIN	Sierra Leone	1988	694	General cargo/ multipurpose	Dromon Bureau of Shipping	Other	Billion Star Marine Services Ltd	16/07/14	21/07/14	EMERGENCY SYSTEMS: emergency fire pump and its pipes/emergency fire pump not working, emergency source of power - emergency generator/emergency generator not working; POLLUTION PREVENTION - MARPOL ANNEX I/oil and oily mixtures from machinery spaces/e/r, tank top bilge water accumulated 80cm in depth; SAFETY OF NAVIGATION: echo sounder/no echo sounding device on board as per requirement of form E of cargo ship equipment certificate

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.