

Ships detained in Hong Kong by PSC Section in August 2014

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	9167851	PACIFIC EXPRESS	Vietnam	1997	8333	Container	Vietnam Register	Vietnam Register	GEMADEPT Corp (Cong Ty Co Phan Dai Ly Lien Hiep Van Chuyen)	11/08/14	12/08/14	LIFE SAVING APPLIANCES: lifejackets incl. provision and disposition/battery for lifejacket was expired since 2010.9; WATER/WEATHERTIGHT CONDITIONS: covers (hatchway-, portable-, tarpaulins, etc.)/one butterfly nut missing and one damaged at poop deck watertight hatch covers; FIRE SAFETY: fire doors/openings in fire-resisting divisions/several self-closing device for emergency escape door were not in order; LIVING AND WORKING CONDITIONS - WORKING CONDITIONS: safe means of access/many valves cover missing on engine room floor, safe means of access/one engine floor was damaged; EMERGENCY SYSTEMS: functionality of safety systems/fuel oil service tanks quick closing valves were blocked by wedges or tied up wires
2	8663729	ALLIANCE	Honduras	1996	1315	Container	C.T.M. Inspection and Classification Company, S. de R.L.	C.T.M. Inspection and Classification Company, S. de R.L.	Sea Rhythm Enterprise Pte Ltd	18/08/14	---	SAFETY OF NAVIGATION: voyage or passage plan/voyage plan for voyage (kaohsiung to Hong Kong) not available for inspection, lights, shapes, sound-signals/navigation stern light sector angle more than 135 deg and upper blub missing; LIFE SAVING APPLIANCES: lifejackets incl. provision and disposition/all lifejackets on board not SOLAS type, rescue boats/rescue boat, keel plate/connection bolts seriously wasted, inflatable liferafts/one liferaft secured to prevent the functionality of hydrostatic device and shortage of one liferaft (not found in place) as per CSE cert; WATER/WEATHERTIGHT CONDITIONS: cargo & other hatchways/cargo hold hatch coaming on port/aft, found numerous areas holed (abt. 1.5m in length) numerous air pipes on deck found holed or temporary covered by cement box, ventilators, air pipes, casings/numerous air pipes on deck found holed or temporary covered by cement box; ISM: maintenance of the ship and equipment/form the evidences above and documentation (e.g. ORB, GRB, maintenances records, etc) the implementation of safety management system on board not effective
3	9228289	BIEN DONG STAR	Vietnam	2000	6899	Container	Nippon Kaiji Kyokai	Vietnam Register	Bien Dong Shipping Co Ltd (Bien Dong)	25/08/14	27/08/14	SAFETY OF NAVIGATION: automatic identification system (AIS)/AIS LCD display not readable/defective; RADIO COMMUNICATIONS: MF/HF radio installation/MF HF LCD display not readable (defective) and no record for DSC test to coast station with acknowledge, antenna shackle broken, and failed HF/DSC test to coast station; LIFE SAVING APPLIANCES: rescue boat inventory/rescue boat, all equipment not stowed on board the boat and not stored in watertight container, remote launching wire seriously corroded and broken, compass base broken, boat navigation all light inco; POLLUTION PREVENTION - MARPOL ANNEX I: oil filtering equipment/OWS, engineer unable to demonstrate auto stopping device as per IOPP certificate

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.