

Ships detained in Hong Kong by PSC Section in September 2014

| No | IMO Number | Ship Name | Flag | YOB | GRT | Ship Type | Class | Related ROs | Ship Company | Date of Detention | Date of Release | Nature of Deficiencies (responsible RO, if any) |
|----|------------|--------------|----------|------|-------|--------------------------------|--|--|--|-------------------|-----------------|---|
| 1 | 9446893 | DONG PENG 58 | Cambodia | 2003 | 4090 | General cargo/ multipurpose | Union Bureau of Shipping | Union Bureau of Shipping | Rongde International Shipping Ltd | 02/09/14 | 05/09/14 | CERTIFICATE AND DOCUMENTATION - DOCUMENTS : records of rest/fake crew rest hour records against ships real operation; WATER/ WEATHERTIGHT CONDITIONS: doors/upper deck accommodation fwd two weathertight doors holed; FIRE SAFETY: fixed fire extinguishing installation/CO ₂ system actuating pipes broken. cylinders numbers for holds not known, fixed fire extinguishing installation/e/r local fire fighting system not operational; SAFETY OF NAVIGATION: echo sounder/echo sounder fails to indicate depth constantly |
| 2 | 8663781 | STAR FORTUNE | Honduras | 2004 | 2989 | Container | C.T.M. Inspection and Classification Company, S. de R.L. | C.T.M. Inspection and Classification Company, S. de R.L. | Star Fortune Enterprises Ltd | 05/09/14 | 12/09/14 | CERTIFICATE AND DOCUMENTATION - SHIP CERTIFICATES: safety management certificate (SMC/ISM Code)/no issue date for SMC and no company IMO no. on SMC and DOC, LIVING AND WORKING CONDITIONS - WORKING CONDITIONS: legal documentation on work and rest hours/no rest hour record for each seafarer on board; CERTIFICATE AND DOCUMENTATION - CREW CERTIFICATES: certificate for medical care/no medical fitness certificate for crew member; SAFETY OF NAVIGATION: echo sounder/echo sounder was out of order, navigation bridge visibility/clear view screen (CVS) out of order; LIFE SAVING APPLIANCES: lifeboats/lifeboat engines cannot be started |
| 3 | 9647174 | XING YANG 7 | Panama | 2010 | 3518 | Bulk carrier | Registro Italiano Navale | Registro Italiano Navale; Overseas Marine Certification Services | Fenghui Maritime Consulting Services Co Ltd | 12/09/14 | 17/09/14 | SAFETY OF NAVIGATION: echo sounder/echo sounder not working, not declared when entering port; CERTIFICATE AND DOCUMENTATION - CREW CERTIFICATES: certificate for rating for watchkeeping/one engine rating taking watches as pers schedule and records, not holding engine-watch certificate; FIRE SAFETY: fixed fire extinguishing installation/e/r and cargo hold CO ₂ system, operation manual not provided, posted instruction incorrect. numbers of cylinders for individual compartments not identified |
| 4 | 8918253 | ZHENG YANG | Panama | 1990 | 17331 | General cargo/ multipurpose | Nippon Kaiji Kyokai | Nippon Kaiji Kyokai | Eastern Rain International Ship Management Co Ltd | 15/09/14 | 18/09/14 | CERTIFICATE AND DOCUMENTATION - DOCUMENTS: records of rest/rest/working hours records for master not available; SAFETY OF NAVIGATION: charts/previous and intended voyage charts BA4127, 3026 small correction, T&P correction not updated for year 2014, speed and distance indicator/speed log not working; RADIO COMMUNICATIONS: facilities for reception of marine safety inform./NAVTEXT not working |

| | | | | | | | | | | | | |
|---|---------|---------------|---------------------------|------|-------|-----------------|--------------------|--------------------------------|--|----------|----------|---|
| 5 | 9209350 | PERARIN | Iran, Islamic Republic of | 2000 | 36014 | Container | Germanischer Lloyd | Iranian Classification Society | Rahbaran Omid Darya Ship Management Co | 17/09/14 | 29/09/14 | SAFETY OF NAVIGATION: voyage or passage plan/no voyage plan available for previous voyage from Chiwan to Hong Kong; RADIO COMMUNICATIONS: facilities for reception of marine safety inform./navtex LCD display, not showing complete information/defective, (no printer connected); FIRE SAFETY: fire detection and alarm system/fire detecting system showing fault alarm/defective for 2 zones; LIFE SAVING APPLIANCES: lifeboats/lifeboat no. 2, unable to start by 2 batteries sets |
| 6 | 9737668 | TRITON JAWARA | Indonesia | 2013 | 1558 | Offshore supply | Bureau Veritas | Bureau Veritas | PT Triton Global Maritim | 24/09/14 | 26/09/14 | CERTIFICATE AND DOCUMENTATION - CREW CERTIFICATES: manning specified by the minimum safe manning doc/short of one engine room rating and not comply with as per MSMD; LIFE SAVING APPLIANCES: rescue boats/rescue boat engine unable to start (patrol fuel tank is empty and no fuel available on board) and equipment not stored on the boat; ISM: other (ISM)/SMS not implemented for emergency, safe manning and shipboard essential operation |
| 7 | 9309447 | MSC RANIA | Panama | 2005 | 94489 | Container | Germanischer Lloyd | Germanischer Lloyd | Mediterranean Shipping Co Srl | 25/09/14 | 26/09/14 | POLLUTION PREVENTION - MARPOL ANNEX I: oil disch. Monitoring and control system/oily water separator not working; PROPULSION AND AUXILIARY MACHINERY/UMS - ship/main engine oil mist detector system isolated due to some detector fault |

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.