

Ships detained in Hong Kong by PSC Section in February 2015

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	9150860	PACIFIC PEARL	Panama	1997	8957	Container	Korean Register of Shipping	Korean Register of Shipping; Nippon Kaiji Kyokai; Germanischer Lloyd	GEMADEPT Corp (Cong Ty Co Phan Dai Ly Lien Hiep Van Chuyen)	02/02/15	03/02/15	SAFETY OF NAVIGATION: charts/voyage charts BA1968, 3026 expired edition in use, nautical publications/nautical publication NP131, NP79, NP283(2), 286(4), NP286(6), NP(30) not official edition; speed and distance indicator/speed log not working; FIRE SAFETY: remote means of control (opening, pumps, ventilation, etc.) machinery spaces/funnel flap unable to be closed properly, ventilation/cargo hold no. 3 goose neck vent pipe corroded holed on top side
2	8896821	HOI HING	Honduras	1993	2758	Container	C.T.M. Inspection and Classification Company, S. de R.L.	C.T.M. Inspection and Classification Company, S. de R.L.	Shun Tin Trading Co Ltd	04/02/15	- - -	CERTIFICATE AND DOCUMENTATION - CREW CERTIFICATES: certificates for master and officers/CoC for C/O, 2/O, 2/E, AB and oiler not available, manning specified by the minimum safe manning doc/short of one engineer as per minimum safe manning cert. issued by class CTM, not issued by flag; SAFETY OF NAVIGATION: gyro compass/all navigation equipment and fire detection system turned off when the ship anchored (including gyro compass/repeater, navtex, GMDSS radio, AIS heading test failed); FIRE SAFETY: fire detection and alarm system/fire detection system failed test by smoke tester, fire-dampers/fire dampers for funnel, e/r ventilators failed to close, O-S label incorrect; LIFE SAVING APPLIANCES: rescue boats/rescue boat, engine manual starting failed, rudder jammed, sheaves wasted, painter missing, flash light for morse signalling and search light not available, hooks wasted, limit switch jammed, compass; EMERGENCY STSTEMS: emergency fire pump and its pipes/emergency fire pump failed to deliver water and crew unable to locate isolating valve; WATER/WEATHERTIGHT CONDITIONS: covers (hatchway-, portable-, tarpaulins, etc.)/ NO. 1 & 2 cargo hold hatch covers, rubber seal damaged/missing
3	9158795	HUA SHUN	Panama	1997	4165	General cargo/ multipurpose	Panama Shipping Registrar Inc.	Panama Shipping Registrar Inc.; Overseas Marine Certification Services	Sun Rising Shipmanagement Co Ltd	06/02/15	13/02/15	FIRE SAFETY: ventilation/numerous vent cover for accommodation unable to be closed, fire detection and alarm system/fire detection and alarm system control panel indicated fault; CERTIFICATE AND DOCUMENTATION - CREW CERTIFICATES: certificate for medical care/cook not hold medical examination certificate, SAFETY OF NAVIGATION: speed and distance indicator/speed log not working, nautical publications/nautical publication NP79, NP286(6), NP283(2), NP203, NP204, IAMSAR vol. III expired edition in use, LIFE SAVING APPLIANCES: lifeboats/lifeboat battery no. 1 fail to start engine; LIVING AND WORKING CONDITIONS - WORKING CONDITIONS: structural features (ship)/main deck hand rails damaged seriously on both sides; ISM: maintenance of the ship and equipment/according to the above listed items, shipboard ISM maintenance of ship equipment not effectively implemented, classification society additional audit shall be carried out before re-inspection arranged

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.