

Ships detained in Hong Kong by PSC Section in July 2015

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	9109952	EAST PROSPERITY	Panama	1994	5471	General cargo/ multipurpose	NK	NK	EASTERN BROTHER SHIPPING CO. LIMITED (HK)	03/07/15	07/07/15	CARGO & OTHER HATCHWAYS: No.1 cargo hold forward hatchway cover damaged/brokenload lines; EMERGENCY FIRE PUMP AND ITS PIPES: Emergency fire pump vacuum pump belt broken, EFP cannot properly deliver water
2	9446893	DONG PENG 58	Cambodia	2003	4090	General cargo/ multipurpose	Union Bureau of Shipping	Union Bureau of Shipping	Rongde International Shipping Ltd	15/07/15	16/07/15	VENTILATORS, AIR PIPES, CASINGS: Sside F.O. Tank Vent Pipe Corroded/Broken; FIRE PUMPS AND ITS PIPES : Fire main pipe I.W.O No.2 Cargo Hold Aft leaking during testing; MAINTENANCE OF THE SHIP AND EQUIPMENT: As evidenced by above deficiencies, Ships SMS cannot ensure proper maintenance of ship
3	8631702	YUN SHIN	Sierra Leone	1988	694	General cargo/ multipurpose	Dromon Bureau of Shipping	Dromon Bureau of Shipping	Billion Star Marine Services Ltd	17/07/15	--	CERTIFICATE FOR RATING FOR WATCHKEEPING: One AB do not hold valid license for navigation watch keeping; flag endorsement for c/o expired; medical certificates for c/o and c/e expired; one AB with navigation watch keeping license, stated iii/4 on the license; CARGO & OTHER HATCHWAYS: Cargo hold hatch coaming holed at port side aft; OTHER (FIRE SAFETY):HFO service & settling tank vent pipe to deck was constructed by plastic hose; OIL AND OILY MIXTURES FROM MACHINERY SPACES: Oily bilge found in engine room; REMOTE MEANS OF CONTROL (OPENING,PUMPS,VENTILATION,ETC.) MACHINERY SPACES: Quick closing valves in engine room gagged; FIXED FIRE EXTINGUISHING INSTALLATION: CO2 system not ready to use and no instruction posted; RESOURCES AND PERSONNEL: As per above evidence, ships ISM is not implemented effectively. Resource and personnel training required.
4	7927180	BORNEO AQUA NO. 2	Sierra Leone	1979	660	Other special activities	New United International Marine Services Ltd.	New United International Marine Services Ltd.	Mark Ship Management & Consultant Co Ltd	23/07/15	31/07/15	FIRE DETECTION AND ALARM SYSTEM: Fire alarm panel indicates power trouble and switches check alarm, tools for testing not available, unable to test the fire detection system.; CHARTS: Nautical charts and publication not available or updated, including chart catalogue, BA charts 937, 4127, 4117, 3483, 1968, etc. for intended voyage, tide table, list of radio signals, NTM last edition.; DOORS: Various w/t doors (including pump room, E/R-pump room, E/R -accommodation) deformed/seized and unable to close.; OIL FILTERING EQUIPMENT: OWS control box defective, test cork and valve (lower) leaking and found oily water.; OTHER (ISM): As per deficiencies above, safety management on board the vessel not implemented effectively.

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.