

Ships Detained in Hong Kong Due to PSC Inspection in November 2017

No.	IMO No.	Ship Name	Flag	YOB	GRT	Ship Type	Classification Society	Related ROs	Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	8921664	PL YUI LAAM	Panama	1989	4025	Container ship	Korean Register of Shipping	Korean Register of Shipping /Panama Maritime Documentation Services	Ocean Grow International Shipmanagement Consultant Corp	07.11.2017	16.11.2017	EMERGENCY SYSTEMS: EMERGENCY FIRE PUMP SEA SUCTION VALVE LOCATED INSIDE E/R NOT ABLE TO OPEN REMOTELY FROM OUTSIDE E/R., RADIO COMMUNICATIONS: MF/HF DSC DISPLAY NOT LEGIBLE AFTER SWITCHED TO DC POWER., WATER/WEATHERTIGHT CONDITIONS: NO.1, 2 AND 3 CARGO HOLD ENTRANCE HATCHES WERE MODIFIED WITHOUT APPROVAL BY FLAG TO PROVIDE SIDE PORTS ON COAMINGS TO ALLOW POWER CABLE OF THE ADDITIONAL GENERATOR ENGINE INSTALLED ON POOP DECK TO LEAD INTO CARGO HOLDS.
2	9167461	KANWAY GLOBAL	Taiwan, Province of China	1997	18502	Container ship	CR Classification Society (CCRS)	CR Classification Society (CCRS)	China Famous Co Ltd	09.11.2017	10.11.2017	WATER/WEATHERTIGHT CONDITIONS: NO.2 CARGO HATCH COVER PORT SIDE FOUND CRACKED ABOUT 1 FOOT AND 4 HOLES., WATER/WEATHERTIGHT CONDITIONS: NO.5 CARGO HOLD HATCH COVER PORT SIDE AND NO.3 CARGO HOLD HATCH COVER PORT SIDE FOUND DAMAGED ON THE GROOVE FOR RUBBER SEAL AND COULD NOT BE CLOSE WEATHER TIGHT., SAFETY OF NAVIGATION: NO.1 AND NO.2 STERN NAVIGATION LIGHTS WERE UNLIT.,