

Ships Detained in Hong Kong Due to PSC Inspection in September 2018

No.	IMO No.	Ship Name	Flag	YOB	GRT	Ship Type	Classification society	Related ROs	Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	8936061	FRIENDSHIP	Niue	1987	991.00	Refrigerated cargo	International Ship Classification	International Ship Classification	Fu Rui Da Int'l Shipping Ltd	12.09.2018	25.10.2018	<p>Safety of Navigation - MULTIPLE BRIDGE EQUIPMENT NOT OPERATIONAL AND/OR MISSING : BNWAS NOT OPERATIONAL, RPM INDICATOR NOT WORKING, TELEPHONE TO STEERING GEAR ROOM NOT WORKING, SPEED LOG NOT AVAILABLE FOR INSPECTION AND RESPONSIBLE OFFICERS NOT ABLE TO DEMONSTRATE OPERATION OF STAND BY NAV LIGHTS.</p> <p>Life saving appliances - RESCUE BOAT ENGINE COULD NOT BE STARTED, RESCUE BOAT FUEL OIL TANK IS HOLED, RESCUE BOAT HOOK SUPPORT ARE WASTED AND RESCUE BOAT DRAIN HOLE NON RETURN MECHANISM IS BROKEN</p> <p>Pollution prevention - OPERATION OF OWS COULD NOT BE SHOWN TO PSCO</p> <p>Pollution prevention - OPERATION OF SEWAGE TREATMENT PLANT COULD NOT BE SHOWN TO PSCO</p> <p>ISM - DEF. FOUND ON VESSEL IS INDICATIVE OF GROSS FAILURE OF VESSEL'S SMS TO ENSURE SAFE OPERATION OF VESSEL, MAINTENANCE OF VESSEL AND EMERGENCY PREPAREDNESS OF VESSEL. (International Ship Classification)</p> <p>Structural Conditions - FORE PEAK STORE STBD SIDE WATERTIGHT DOOR TO BOSUN STORE DAMAGED AND GASKET IS MISSING. LOSS OF WATER TIGHTNESS</p> <p>Structural Conditions - E/R STBD SIDE, BETWEEN FRAME 6 AND FRAME 10, 3 TRANSVERSE DECK BEAMS AND BRACKETS WERE NOT WELDED WITH DECK PLATE.</p> <p>Structural Conditions - FORE CASTLE STBD SIDE DECK AND PORT SIDE DECK DAMAGED WITH 7 HOLES, THE LARGEST HOLE IS ABOUT 40CM BY 20CM</p> <p>Fire safety - MULTIPLE FIRE HYDRANTS IN ER AND ON DECK ARE DAMAGED AND CANNOT BE OPERATED.</p>