

Ships Detained in Hong Kong Due to PSC Inspection in April 2019

No.	IMO No.	Ship Name	Flag	YOB	GRT	Ship Type	Classification society	Related ROs	Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	9095412	MONIKA	Togo	2004	2996	General cargo / multipurpose	Union Bureau of Shipping	Union Bureau of Shipping	Uni-World Shipping Ltd	15.04.2019	19.04.2019	<p>Safety of Navigation - 1 RADAR (9 GHZ) WAS MALFUNCTIONED.</p> <p>Safety of Navigation - SEVERAL NAVIGATIONAL AND SIGNAL LIGHTS COULD NOT BE ILLUMINATED.</p> <p>Safety of Navigation - LATEST EDITIONS OF SEVERAL NAUTICAL CHARTS FOR LAST AND INTENDED VOYAGES WERE NOT ONBOARD. SEVERAL NAUTICAL CHARTS FOR LAST AND INTENDED VOYAGES WERE NOT UPDATED.</p> <p>Safety of Navigation - ECHO SOUNDER WAS MALFUNCTIONED.</p> <p>ISM - ALL DEFICIENCIES (FOUND OUT IN PSC INSPECTION) WERE OBJECTIVE EVIDENCES WHICH SHOWED THAT THERE WAS A FAILURE IN ENSURING VESSEL TO BE MAINTAINED EFFECTIVELY ACCORDING TO SMS AND ISM CODE.</p> <p>Fire safety - 1 FIRE-FIGHTER'S OUTFIT WAS LEAKING SERIOUSLY. REQUIREMENTS OF SOLAS COULD NOT BE FULFILLED.</p> <p>Fire safety - HOLES APPEARED ON FIRE MAIN LINE AT FORWARD AND THUS IT WAS LEAKING SERIOUSLY.</p>
2	9290218	MON TOK	Indonesia	2003	7320	General cargo / multipurpose	Nippon Kaiji Kyokai	Biro Klasifikasi Indonesia	PT Pelayaran Andalas Bahtera Baruna	17.04.2019	23.04.2019	<p>Safety of Navigation - LATEST EDITIONS OF SEVERAL NAUTICAL CHARTS FOR LAST AND INTENDED VOYAGES WERE NOT ONBOARD. SEVERAL NAUTICAL CHARTS FOR LAST AND INTENDED VOYAGES WERE NOT UPDATED.</p> <p>Safety of Navigation - LATEST EDITIONS OF SEVERAL NAUTICAL PUBLICATIONS FOR LAST AND INTENDED VOYAGES WERE NOT ONBOARD. FOR EXAMPLE, SAILING DIRECTIONS, LIST OF RADIO SIGNALS AND IAMSAR MANUAL VOLUME III. SEVERAL NAUTICAL PUBLICATIONS FOR LAST AND INTENDED VOYAGES WERE NOT ONBOARD.</p> <p>Life saving appliances - ENGINES OF BOTH SIDES OF LIFEBOATS COULD NOT BE STARTED BY ANY MEANS.</p> <p>Certificate and Documentation - SHIP ENERGY EFFICIENCY MANAGEMENT PLAN WAS NOT ONBOARD.</p> <p>ISM - ALL DEFICIENCIES (FOUND OUT IN PSC INSPECTION) WERE OBJECTIVE EVIDENCES WHICH SHOWED THAT THERE WAS A FAILURE IN ENSURING VESSEL TO BE MAINTAINED EFFECTIVELY ACCORDING TO SMS AND ISM CODE.</p> <p>Emergency Systems - LOTS OF EMERGENCY LIGHTS COULD NOT BE ILLUMINATED.</p> <p>Radio Communications - INMARSAT C WAS MALFUNCTIONED. PV TEST COULD NOT BE DONE. MESSAGE COULD NOT BE SENT OUT.</p> <p>Fire safety - CONNECTION COUPLINGS (TO AIR BOTTLES) OF 2 FIRE-FIGHTER'S OUTFITS WERE BROKEN. AIR BOTTLES COULD NOT BE CHANGED. REQUIREMENTS OF SOLAS COULD NOT BE FULFILLED.</p>
3	7508336	WAN JING HONG	Mongolia	1977	3624	Refrigerated cargo	Singclass International	Singclass International	GOLDEN LAMP STAND SHIPPING SAFETY MANAGEMENT CONSULTANT CO LTD	29.04.2019	10.05.2019	<p>Safety of Navigation - NO. 2 RADAR (9 GHZ) WAS MALFUNCTIONED.</p> <p>Safety of Navigation - LATEST EDITIONS OF SEVERAL NAUTICAL CHARTS FOR LAST AND INTENDED VOYAGES WERE NOT ONBOARD. SEVERAL NAUTICAL CHARTS FOR LAST AND INTENDED VOYAGES WERE NOT UPDATED.</p> <p>Safety of Navigation - BRIDGE NAVIGATIONAL WATCH ALARM SYSTEM WAS MALFUNCTIONED.</p> <p>Certificate and Documentation - ANNUAL VERIFICATION RECORD OF DOC COULD NOT BE FOUND OUT.</p> <p>Certificate and Documentation - SHIPBOARD OIL POLLUTION EMERGENCY PLAN WAS NOT ONBOARD.</p> <p>Certificate and Documentation - SHIP ENERGY EFFICIENCY MANAGEMENT PLAN WAS NOT ONBOARD.</p> <p>Pollution prevention - GARBAGE MANAGEMENT PLAN WAS NOT ONBOARD.</p> <p>ISM - ALL DEFICIENCIES (FOUND OUT IN PSC INSPECTION) WERE OBJECTIVE EVIDENCES WHICH SHOWED THAT THERE WAS A FAILURE IN ENSURING VESSEL TO BE MAINTAINED EFFECTIVELY ACCORDING TO SMS AND ISM CODE.</p> <p>Fire safety - 1 FIRE-FIGHTER'S OUTFIT WAS LEAKING SERIOUSLY. REQUIREMENTS OF SOLAS COULD NOT BE FULFILLED.</p>