

Ships Detained in Hong Kong Due to PSC Inspection in December 2019

No.	IMO No.	Ship Name	Flag	YOB	GRT	Ship Type	Classification society	Related ROs	Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	9111450	PL YUI LAAM	Belize	1994	9600	Container Ship	New United International Marine Services Ltd.	New United International Marine Services Ltd.	Ming Jin Shipmanagement Consultant Ltd	17.12.2019	07.01.2020	<p>Doors - AT THE WATERTIGHT DOOR OF ESCAPE TRUNK ON MAIN DECK, RUBBER GASKET STEEL CHANNEL WAS FOUND BROKEN (ABOUT 0.8M IN LENGTH), WHICH LOSES ITS WATER-TIGHTNESS. Covers (hatchway-, portable-, tarpaulins, etc.) - THE STARBOARD SIDE ACCESS HATCH COVER ON MAIN DECK TO WORKSHOP OF ENGINE ROOM CAN NOT BE FULLY CLOSED. ON THE HATCH COAMING, TWO HOLES WERE FOUND (ABOUT 15CM X 5CM EACH). ACCESS HATCH ON MAIN DECK TO PASSAGEWAY STARBOARD SIDE CAN NOT BE FULLY CLOSED.</p> <p>Lifeboats - LIFEBOAT ENGINE CAN NOT BE STARTED BY EITHER BATTERY.</p> <p>Maintenance of the ship and equipment - DEFICIENCIES ABOVE INDICATE THAT THE FAILURE OF COMPANY MANAGEMENT SYSTEM TO PROVIDE SUPPORT AND RESOURCES TO MAINTAIN SHIP EFFECTIVELY AND ACCORDING TO SMS AND ISM CODE</p>