

Ships Detained in Hong Kong Due to PSC Inspection in May 2021

No.	IMO No.	Ship Name	Flag	YOB	GRT	Ship Type	Classification society	Related ROs	Company	Date of Detention	Date of Release	Nature of Detainable Deficiencies (responsible RO, if any)
1	9528419	YONG SHUN	Belize	02.06.2008	7460	General Cargo Ship	BV	ICS (ISM)	Guo Xing Ship Management Co Ltd	12.05.2021	15.05.2021	<p>1. Both side of FWD emergency embarkation lights for liferaft were found unlit;</p> <p>2. Engine room tank top was found over 10cm depth of oily water and E/R L.O. purifier pump save all was found oil;</p> <p>3. Air vent head's valve sealing ring of No. 2 Ballast water tank (S) was detached; and</p> <p>4. The deficiency no. 1 to 12 in the PSC inspection report indicated that the SMS implemented onboard failed to ensure the ship's effective maintenance.</p>
2	8704327	PEARL NO.2	Sierra Leone	01.05.1987	1967	General Cargo Ship	UBS	UBS	Sea Commander Shipping SA	17.05.2021	29.05.2021	<p>1. No validate of Document of Compliance onboard, the Interim of DOC was expired on 14 April 2020;</p> <p>2. Portable Daylight Signaling Lamp was defective, it can't be switched on using battery or shipboard electrical supply mode;</p> <p>3. Air horn by manually pulling are not working during demonstration to PSCO;</p> <p>4. None of closing device at the Aft (P&S) goose neck type air vent, engine room hatch cover hinges damaged and No.1 ballast water. tank vent head closing float valve with rubber sealing ring were missing;</p> <p>5. Lifeboat engine's start up battery was not available;</p> <p>6. Plenty of oil was accumulated around main engine's foundation bolts area;</p> <p>7. One of the fire hose with its connection located at starboard deck was found leakage seriously; and</p> <p>8. The deficiency no. 2 to 12 in the PSC inspection report indicated that the SMS implemented onboard failed to ensure the ship's effective maintenance.</p>