

Ships Detained in Hong Kong Due to PSC Inspection in November 2022

| No. | IMO No. | Ship Name | Flag | Date of Keel Laid | GRT | Ship Type | Classification society | Related ROs | Company | Date of Detention | Date of Release | Nature of Detainable Deficiencies (responsible RO, if any) |
|-----|---------|--------------|--------|-------------------|------|---------------------------|--------------------------------|--------------------------------|--------------------------------|-------------------|-----------------|---|
| 1 | 9158537 | YONG XIANG 9 | Panama | 20.09.1997 | 9298 | Refrigerated Cargo Vessel | Panama Shipping Registrar Inc. | Panama Shipping Registrar Inc. | East Maritime Service Co. Ltd. | 04.11.2022 | 17.11.2022 | <ol style="list-style-type: none"> 1. Numerous of fire hoses and nozzles were not available on deck and a fire nozzle was missing in 3rd floor of engine room; 2. Sewage treatment plant was inoperative and out of order; 3. Both sides of lifebuoys for MOB were found smoke signal/light expired; 4. Oily water separator was inoperative and the engineers were not familiar with using O.W.S; 5. The deficiencies in the PSC report (Form B) shown that the ship's SMS implementation failure on maintenance and effective operation. |