

Ships Detained in Hong Kong Due to PSC Inspection in August 2023

No.	IMO No.	Ship Name	Flag	Date of Keel Laid	GRT	Ship Type	Classification society	Related ROs	Company	Date of Detention	Date of Release	Nature of Detainable Deficiencies (responsible RO, if any)
1	9518593	XIN HAI 788	Belize	21.07.2007	2992	General cargo/multipurpose	Intermaritime Certification Services, ICS Class	Intermaritime Certification Services, ICS Class	Xinhai Marine Co, Limited	31.08.2023	11.09.2023	<ol style="list-style-type: none"> 1. Batteries for GMDSS cannot supply electrical power for MF/HF DSC Call Test; 2. The boiler flame failure alarm cannot be demonstrated in operative condition during inspection; 3. Voyage & Passage Plan was not prepared with necessary information for the last voyage from 'Haiphong, VIETNAM' to 'Hong Kong, CHINA'. (such as ship draught, under keel clearance on way points, contingency measure on abort point, emergency anchorage); 4. Emergency Escape door self-closing device near ECR was not working; 5. Fire detectors on top of purifier cannot demonstrate to be operative during inspection; 6. Quick Closing Valves for Lubricating Oil & Fuel Oil Tanks, the remote control (Activation Point located at 'Messroom' and at 'Accommodation Corridor on Main Deck') do not provide with eligible indication for the corresponding tanks (service zone). It was blocked by obstacles and the crew cannot perform the closing of specific valve in few attempts; and 7. The implementation of ship's ISM failed to ensure proper maintenance of the ship with objective evidence of above deficiency items.