

Ships Detained in Hong Kong Due to PSC Inspection in March 2024

No.	IMO No.	Ship Name	Flag	Date of Keel Laid	GRT	Ship Type	Classification society	Related ROs	Company	Date of Detention	Date of Release	Nature of Detainable Deficiencies (responsible RO, if any)
1	9118410	PRIMROSE 6969	Panama	27.09.1994	39560	Woodchip Carrier	Isthmus Bureau of Shipping, S.A.	N/A	VAN LOC HUNG INTERNATIONAL SEA SHIPPING CO., LTD.	2024-03-22	2024-03-27	<p>1. Emergency fire pump was not working during inspection.</p> <p>2. Two isolation valves were not working in the fire control station.</p> <p>3. Stbd Lifeboat cannot perform ahead and astern function during inspection.</p> <p>4. Several snap locks for hatch covers were found damaged during inspection.</p> <p>5. Cargo hold 6 ventilation head damper was not working.</p> <p>6. Engine room bilge well alarms were not working.</p> <p>7. Oil accumulated around the diesel generators.</p> <p>8. No.2 boiler feed pump was found leaking at shaft seal.</p> <p>9. The Implementation of ship's ISM failed to ensure proper maintenance of the ship with objective evidence of above deficiencies..</p>