

Ships Detained in Hong Kong Due to PSC Inspection in March 2025

No.	IMO No.	Ship Name	Flag	Date of Keel Laid	GRT	Ship Type	Classification society	Related ROs	Company	Date of Detention	Date of Release	Nature of Detainable Deficiencies (responsible RO, if any)
1	8730895	CAMILLA	Indonesia	01.03.1997□	7,258	General cargo/multipurpose	Biro Klasifikasi Indonesia	Biro Klasifikasi Indonesia	PT Pelayaran Andalas Bahtera Baruna	4.03.2025		1. Emergency generator unable to automatically start and supply power to emergency switchboard during blackout test. 2. The Oil Water Separator (OWS) failed to function properly during operational testing. 3. The combined deficiencies 1-21 are objective evidence that the SMS as implemented fails to ensure the ship is maintained as required by ISM
2	8532372	STAR JANET	United Republic of Tanzania	08.01.2006	500	General cargo/multipurpose	HORIZON BUREAU OF SHIPPING	HORIZON BUREAU OF SHIPPING	HONG-LI COMPANY LTD	13.03.2026		1. Hatch coaming found cracked in several locations and holed. 2. Multiple generators were inoperative. 3. The port side anchor was missing. 4. Crew certificates of competency did not have flag state endorsement. 5. Most of radio equipment listed in Form R of the Safety Radio Certificate were not available. 6. The sewage treatment plant was inoperative. 7. Nautical charts and passage plans for previous voyage were not available. 8. Most of the equipment listed in Form E of the Cargo Ship Safety Equipment Certificate was not equipped. 9. The Oily Water Separator (OWS), associated tank, and documentation in Form A of the IOPP Certificate were not available. 10. There were no records of fire alarm system testing, and the fire detection system was not operational. 11. The emergency fire pump was inoperative.