

Ships Detained in Hong Kong Due to PSC Inspection in October 2025

No.	IMO No.	Ship Name	Flag	Date of Keel Laid	GRT	Ship Type	Classification society	Related ROs	Company	Date of Detention	Date of Release	Nature of Detainable Deficiencies (responsible RO, if any)
1	9321093	LADY VIOLETTA	Panama	28.05.2004	7,767	General cargo/multipurpose	RINA	RINA	GN Denizcilik ve Acentelik Ltd Sti	31.10.2025		1.The free fall lifeboat engine failed to start. 2.The rescue boat outboard engine could not be controlled or steered from the coxswain position. The rescue boat was modified without RO approval. The rescue boat canopy, compass, and searchlights were not lit. 3.Numerous transport pins on fixed CO2 system cylinders were not removed. 4.The implementation of ISM system was failed to ensure proper maintenance of the ship, the objective evidence is listed in the detected deficiencies. Additional ISM verification by RO is required.