Appendix G

MARKING SCHEME

Screening Stage

Acceptable Technical Capability

Principal Items/Requirements Are Provided

Marking Stage



1. develop quality elements (checklist) for each quality criterion;
2. assign weight and point to each quality element;
3. calculate the total weighted point (Q) of each tender for each quality criterion;
4. the max. quality score (M) will be assigned to tender with highest quality points (Q_{max})

Price Score Formula

Price Score = 60 * (P_{min} / P)

Notes:

Lowest Tender Price - P_{min}

Individual Tender Price - P

Quality Criteria	Maximum Score (M)	Scores (For Each Quality Criterion)
Ship's Performance	10	$\text{Score} = \frac{M * Q}{Q_{max}}$
Quality of Outfitting Machinery & Equipt.	10	Notes:
Shipyard Facilities, Delivery Programme & Tender Document	5	Max. score of each quality criterion - M Quality points of individual tender - Q
Ship's Functional Achievement	5	Max. quality points obtained among tenderers - Q_{max}
Operation and Maintenance	10	
Passing Mark of Final Quality Score ≥ 20 Marks		

Total Scores

Acceptable Financial Capability