



香港商船資訊

HONG KONG MERCHANT SHIPPING INFORMATION NOTE

Reporting Alleged Inadequacies of Port Reception Facilities

To : Shipowners, Ship Managers, Operators and Masters

Summary

This Note advises the use of the revised consolidated format for reporting alleged inadequacies of port reception facilities.

1. The Marine Environment Protection Committee (MEPC) at its 56th Session in July 2007 approved the revised consolidated format for reporting alleged inadequacies of port reception facilities as set out at annex to the MEPC/Circ.469/Rev.1. A copy of Circular MEPC/Circ.469/Rev.1 is annexed to this Note.
2. Ship masters are urged to use the revised consolidated format to report alleged inadequacies of port reception facilities to this Administration, and to the Authorities of the concerned port State if possible.
3. Shipping companies should include the provisions of the MEPC/Circ.469/Rev.1 in their procedures for shipboard operations required under section 7 of the ISM Code.
4. This Merchant Shipping Information Note supersedes Merchant Shipping Information Note No. 39/2005.

Marine Department
Multi-lateral Policy Division

12 September 2007