No.: **63/2016**

Telephone No. : (852) 2852 3001 Fax No. : (852) 2544 9241

E-mail: hkmpd@mardep.gov.hk

Web site: http://www.mardep.gov.hk



香 港 商 船 資 訊

HONG KONG MERCHANT SHIPPING INFORMATION NOTE

Unified Interpretations relating to the **Application** Regulation II-1/3-6. As Amended. the Revised **Technical** and **Provisions** Means Access Inspections (Resolution for of for MSC.158(78))

To: Shipowners, Ship Managers, Ship Operators, Masters, Classification Societies and Shipbuilders

Summary

The purpose of this Note is to promulgate the unified interpretation relating to the application of SOLAS regulation II-1/3-6, as amended, and the *Revised technical provisions for means of access for inspections* (resolution MSC.158(78)), with a view to ensuring a uniform approach towards the application of the amended SOLAS regulation II-1/3-6 as to the configuration of installing the adjacent sections of vertical ladder in implementing the safe means of access for inspection.

- 1. The Maritime Safety Committee (MSC) of the International Maritime Organization (IMO), at its 96th session in May 2016, approved the unified interpretation of SOLAS regulation II-1/3-6, as amended, and the *Revised technical provisions for means of access for inspections* ("technical provisions") as adopted by resolution MSC.158(78), with a view to ensuring a uniform approach towards the application of the amended SOLAS regulation II-1/3-6 incorporating paragraphs 3.13.2 and 3.13.6 of the technical provisions which set out proper arrangement of adjacent sections of vertical ladders through a linking platform whereby safe means of access for inspection can be enabled.
- 2. The details of the unified interpretation as annexed to IMO circular MSC.1/Circ.1545 can be found in the attachment to this Note on the website of Marine Department (http://www.mardep.gov.hk/en/msnote/msin.html).
- 3. Shipowners, ship managers, ship operators, masters, classification societies and shipbuilders of Hong Kong registered ships should use the unified interpretation when applying the relevant provisions of SOLAS regulation II-1/3-6.

Marine Department Multi-lateral Policy Division

16 December 2016