

MARINE DEPARTMENT NOTICE NO. 113 OF 2007

(Establishment, Withdrawal and Changes of Aids to Navigation,
Fairways, Anchorages & Other Port Facilities)

Floating Barriers Across Tolo Channel

NOTICE IS HEREBY GIVEN that seven mooring buoys marked TC1, TC2, TC3, TC4, TC5, P13 and S32 have been laid on a line joining the following coordinates (WGS 84 Datum) in Tolo Channel:-

(A) 22° 29.120' N 114° 18.563' E

(B) 22° 28.608' N 114° 18.948' E

2. Floating barriers have been laid between the mooring buoys extending to coordinates (A) and (B). Police launches and a barge are in attendance at these barriers.

3. A navigable passage with a width of 250 metres has been provided between buoys TC3 and TC4 for the free movement of vessels. On occasion, this passage may be closed without prior notice. If vessels wish to transit the passage and find it is closed, the coxswain, master or person-in-charge of the vessel should contact the police on site. Advance arrangements for transit may also be made by contacting the Assistant Divisional Commander, Operations on telephone number 3660 8554 or facsimile 2200 4480, who can also provide any further information.

4. The mooring buoys may be lit or unlit subject to operational requirements. Vessels navigating in the vicinity should proceed with extreme caution and pay special attention to any signals displayed or made by the police on site.


5. This notice supersedes Marine Department Notice No. 90 of 2002. A drawing showing the approximate position of the floating barriers is attached to this Notice.

H. P. Liu
Director of Marine(Ag.)

Marine Department
Government of the HKSAR
Date: 13 July 2007
Action File Ref: PA/S 909/106/1(25)

海事處佈告 2007年 第 113 號附圖

Drawing Attached to Marine Department Notice No. 113 of 2007



不宜作航行用途
NOT TO BE USED FOR NAVIGATION