

Ships detained in Hong Kong by PSC Section in May 2011

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	9407172	ZHEN HUA 69	Cambodia	2005	2986	Container ship	Union Bureau of Shipping	Union Bureau of Shipping	Yantai Xiaochuan Shipping Co Ltd	03/05/11	06/05/11	SAFETY OF NAVIGATION: magnetic compass, steering compass shows 20 degrees lower than gyro compass, lights, shapes, sound-signals, ship's whistle was out of work; LIFESAVING APPLIANCES: lifeboats, the rudder of starboard lifeboat was seized, maintenance a
2	9023500	CHEN QI JIE	Cambodia	1994	1209	General cargo/multi-purpose ship	Union Bureau of Shipping	Union Bureau of Shipping	Wuhan Longxun Shipping Management Co. Ltd.	13/05/11	17/05/11	SAFETY OF NAVIGATION: navigation bridge visibility, wheelhouse front window damaged, navigation bridge visibility, two front windows in lower deck found damaged, navigation bridge visibility, wheelhouse front clear view screen cvs belt found damaged; FIRE SAFETY MEASURES: ventilation, s/s engine room ventilator found damaged
3	8604541	XING TAI 1	Mongolia	1986	2383	General cargo/multi-purpose ship	Singclass	Singclass	Xing Tai International Trading Co. Ltd.	16/05/11	18/05/11	MARPOL - ANNEX I: 15 ppm alarm arrangements, 15 ppm alarm of oily water separator was not working, oil record book, 4 pages not signed and can not show any oil sludge disposal notes; FIRE SAFETY MEASURES: fire fighting equipment and appliances, 3 fire fighting hoses holded and are leaking while testing, connectors are leaking, doors within main vertical zone, self close device of door in bridge was taken away; CREW AND ACCOMMODATION (ILO 147): access/structure, external accommodation stairs, 3 steps rust (abt 7 x 8 cm holes); MARPOL - ANNEX V: garbage record book, the records were not complete and can not show any garbage disposal notes; MARPOL RELATED OPERATIONAL DEFICIENCIES: oil and oily mixtures from machinery spaces, e/r accumulated oil every where, is very oily dirty
4	9603867	TONG CHENG 602	Panama	2010	2981	General cargo/multi-purpose ship	Panama Maritime Documentation Services	Panama Maritime Documentation Services; Overseas Marine Certification Services	Bao Xin Marine United	16/05/11	30/05/11	SHIP'S CERTIFICATES AND DOCUMENTS: tonnage, tonnage certificate is out of date, CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for Master and officer, 2nd officer's licence is out of date, SAFETY OF NAVIGATION: nautical publications, itu-list of ship's station; iamsar manual vol.iii are missing; WORKING SPACES (ILO 147): safe means of access, self-closing device for engine room escape door is missing; LOAD LINES: covers (hatchway-, portable-, tarpaulins, etc.), watertight hatch cover on main deck for steering gear room, one locking device is missing
5	9107057	VAN LY	Viet Nam	1993	4879	Container ship	Vietnam Register	Viet Nam Register of Shipping	Bien Dong Shipping Company	19/05/11	20/05/11	SAFETY OF NAVIGATION: echo-sounding device, echo sounder was found defective; LIFESAVING APPLIANCES: lifeboat inventory, lifeboat sea anchor was wasted, holed, torn, launching arrangements for survival craft, lifeboat davit limit switches seized
6	9015527	HANJIN OSAKA	Liberia	1991	51754	Container ship	American Bureau of Shipping	American Bureau of Shipping	V Ships (Germany) Gmbh Co KG	24/05/11	25/05/11	MARPOL - ANNEX I: 15 ppm alarm arrangements, ows 15 ppm content meter and alarm not working; LIFESAVING APPLIANCES: stowage of lifeboats, lifeboat davits limit switch found seized

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.