

## **Ships detained in Hong Kong by PSC Section in September 2013**

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	9634696	MCC SHENZHEN	Antigua and Barbuda	2013	17769	Container Ship	Germanischer Lloyd	Germanischer Lloyd	Uniteam Marine Shipping GMBH	25/09/13	25/09/13	SAFETY OF NAVIGATION: nautical publications/nautical publications not available onboard, such as notices to mariner, IAMSAR Vol III and international code of signal; FIRE SAFETY: fire detection and alarm system/fire detector in zone 10 out of work; RADIO COMMUNICATIONS: MF/HF radio installation/MF/HF DSC (GMDSS station) failed to supply emergency power; STRUCTURAL CONDITIONS: electrical installations in general/220V low insulation alarm found in e/r and emergency generator room.

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.