

3. Ships detained in Hong Kong by PSC Section in March 2016

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	8844373	SHOWA MARU	Togo	1990	498	General cargo	Universal Maritime Bureau Ltd	Universal Maritime Bureau Ltd	Dalian Heyang Shipping Agency Co Ltd	03.03.2016	09.03.2016	SAFETY OF NAVIGATION: VOYAGE PLAN, NOT INCLUDED ESSENTIAL INFORMATION FOR SAFE NAVIGATION AND PASSAGE MONITORING , AND REQUIRED NAUTICAL CHARTS, NO POSITION RECORDS FOR POSITION FIXES, AS SHIP USED PHOTO COPIES OF CHARTS, LIFE SAVING APPLIANCES: RESCUE BOAT , ALL ROUND WHITE CANOPY LIGHT UNLIT, RELEASE CONTROL FOR THE ON-LOAD RELEASE HOOKS UNABLE TO LOCATE, SEARCH LIGHT CRACKED/DAMAGED, WATER/WEATHERTIGHT CONDITIONS: AIR PIPES, AT LEAST 4 PCS FOUND DEFECTIVE/SEIZED, INCLUDING WBT (2P, 2S, 3S AND 3P), FIRE SAFETY: E/R VENTILATORS (P&S) , WASTED/DEFECTIVE DAMPERS, ISM: FROM THE EVIDENCES ABOVE (ITEMS 1-17 , SMS AS IMPLEMENTED, COMPANY NOT ENSURE EFFECTIVE SAFETY MANAGEMENT ON BOARD AS PER ISM CODE REQUIREMENTS.
2	8415873	XIANG SHENG	Cambodia	1984	1209	General cargo/multipurpose	Union Bureau of Shipping	Union Bureau of Shipping	Oceanwin Int'l Shipping Ltd	16.03.2016	24.03.2016	EMERGENCY SYSTEMS: EMERGENCY FIRE PUMP NOT WORKING DURING TEST., STRUCTURAL CONDITIONS: NO "STABILITY BOOKLET" ON BOARD VESSEL., CERTIFICATE & DOCUMENTATION: NO SOPEP ON BOARD THE VESSEL.,

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.