

3. Ships detained in Hong Kong by PSC Section in August 2016

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	9173305	PACIFIC CAPE	Marshall Islands	1999	61764	Oil tanker	Korean Register of Shipping	Korean Register of Shipping/Det Norske Veritas	Thome Ship Management Pte Ltd	25.08.2016	29.08.2016	FIRE SAFETY: 1. FORWARD FIRE DAMPER OF NO.1 E/R FAN NOT CLOSED FULLY (HAS ABOUT 3 CM GAP BETWEEN EACH BLADES) AND AFT FIRE DAMPER HAS GAP ABOUT 2 MM ON THE TOP OF THE BLADE, FORWARD FIRE DAMPER OF NO.3 E/R FAN HAS ABOUT 2 MM GAP ON THE TOP OF TWO BLADES, ISM: BASE ON THE ABOVE DEFICIENCIES, THE VESSEL NOT IMPLEMENTED SHIPBOARD SAFETY MANAGEMENT SYSTEM PROPERLY.
2	9639103	MING HENG 1	Belize	2011	5153	General cargo /multipurpose	Isthmus Bureau of Shipping	Isthmus Bureau of Shipping /Panama Maritime Documentation Services	Fujian Hengfeng Shipping Co Ltd	27.08.2016	30.08.2016	LIFE SAVING APPLIANCES: 6. THE PORT SIDE LIFE BOAT COULD NOT BE CONTROLLED AHEAD, ASTERN AND NEUTRAL WHEN PSCO GAVE TESTING ORDERS, FIRE SAFETY: 10. THE FIRE AND SMOKE DETECTION SYSTEM FOR WHEEL HOUSE, ACCOMMODATION AND ENGINE ROOM MALFUNCTION, ISM: 13. BASE ON THE ABOVE DEFICIENCY, THE SHIP NO IMPLEMENTED SHIP BOARD MANAGEMENT SYSTEM PROPERLY.

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.