

3. Ships detained in Hong Kong by PSC Section in November 2016

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	8659326	JIN CHENG 3	Panama	2004	2965	General cargo/multipurpose	Overseas Marine Certification	Overseas Marine Certification/Intermaritime Certification Services	Ming Jin Shipmanagement Consultant Ltd	26.11.2016	10.1.2017	WATER/WEATHER TIGHT CONDITIONS: WEATHER TIGHT DOOR ON MAIN DECK TO E/R HOLED, GASKET AND GASKET CHANNEL BAR BROKEN. WEATHER TIGHT DOOR OF BOSUN STORE GASKET AND GASKET CHANNEL BAR BROKEN, FIRE SAFETY: FIRE MAIN ON PORT SIDE DECK HOLED, EMERGENCY SYSTEMS: EMERGENCY GENERATOR CANNOT START UP, FIRE SAFETY: PORT SIDE E/R VENT FAN DAMPER CANNOT CLOSE, AND DAMPER SHAFT BROKEN, FIRE SAFETY: FIRE DETECTION SYSTEM OUT OF ORDER, FIRE ALARM CALL POINTS AND SMOKE DETECTOR NO RESPOND,

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.