

## Ships Detained in Hong Kong Due to PSC Inspection in July 2017

No.	IMO No.	Ship Name	Flag	YOB	GRT	Ship Type	Classification Society	Related ROs	Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	8510128	SHUN FA 19	Togo	1985	1491	General cargo/multi purpose	Union Bureau of Shipping	Union Bureau of Shipping	Wealth Ocean Ltd	13.07.2017	19.07.2017	<b>SAFETY OF NAVIGATION:</b> MALFUNCTION OF ECHO SOUNDER, NO CORRECTIVE ACTION TAKEN AGAINST THE DEFICIENCY GIVEN BY PSCO ON 17.01.2017, <b>ISM:</b> SAFETY MANAGEMENT SYSTEM AS IMPLEMENTED ONBOARD NOT ABLE TO ENSURE EFFECTIVE MAINTENANCE OF SHIP AS EVIDENCED BY DEFICIENCIES ITEM NO. 1, 2, 3, 7, 8, 9 AND 12.
2	9571741	DOLPHIN 15	Vietnam	2008	2963	General cargo/multi purpose	Vietnam Register	Vietnam Register	ITC International Transport & Trading JSC	20.07.2017	25.07.2017	<b>SAFETY OF NAVIGATION:</b> SPEED MEASURING DEVICE (THROUGH WATER) ERROR DISPLAY (-20.5 KNOTS DURING SHIP AT ANCHOR), <b>RADIO COMMUNICATIONS:</b> MF/HF DSC FAIL TO POWER ON BY EMERGENCY POWER (DC BATTERY), <b>FIRE SAFETY:</b> PORT AND STARBOARD SIDES E/R FAN DAMPERS CANNOT CLOSE, <b>SAFETY OF NAVIGATION:</b> STERN NAVIGATION LIGHT VISIBLE ANGLE OVER 135 DEG (ABOUT 180 DEG). PORT NAVIGATION LIGHT UPPER AND LOWER BACK SCREEN NOT FIXED ON SAME ANGLE. RED LIGHT CASING HOLED (ABOUT 3CM DIAMETER). STARBOARD NAVIGATION LIGHT GREEN CASING CRACKED.
3	9267546	SINA	Saint Kitts and Nevis	2002	18931	Refrigerated cargo	Nil	Nil	Compass Shipping & Trading Ltd	31.07.2017	03.08.2017	<b>CERTIFICATE &amp; DOCUMENTATION:</b> SHORT OF TWO AB (II/5) AS PER REQUIRED BY MINIMUM SAFE MANNING CERTIFICATE, <b>CERTIFICATE &amp; DOCUMENTATION:</b> MASTER AND CHIEF ENGINEER HAVE NO CERTIFICATES OF ENDORSEMENT ISSUED BY FLAG, AS PER REQUIRED BY FLAG DISPENSATION LETTER DATED 28 JULY 2017.