

MARINE DEPARTMENT NOTICE NO. 125/2023

(Establishment, Withdrawal and Changes of Aids to Navigation,
Fairways, Anchorages & Other Port Facilities)

Establishment of Concrete Pontoon Floating Barriers at Hei Ling Chau Typhoon Shelter

NOTICE IS HEREBY GIVEN that three concrete pontoon floating barriers have been established to attenuate the local wind-generated wave at Hei Ling Chau Typhoon Shelter. The positions of the established concrete pontoon floating barriers and the particulars of the lights are as follows:

Floating barrier 1: Along the north-south direction with approximately 4 metres in width and 100 metres in length within the following coordinates (WGS 84 Datum) from (A) to (D):

	<u>Latitude</u>	<u>Longitude</u>
(A)	22° 14.934'N	114° 01.820'E
(B)	22° 14.891'N	114° 01.855'E
(C)	22° 14.889'N	114° 01.853'E
(D)	22° 14.933'N	114° 01.818'E

The particulars of the lights for **Floating barrier 1** are as follows:

	<u>Latitude</u>	<u>Longitude</u>	<u>Characteristics</u>
(i)	22° 14.933'N	114° 01.819'E	FL yellow 5s
(ii)	22° 14.890'N	114° 01.854'E	FL yellow 5s

Floating barrier 2: Along the east-west direction with approximately 5 metres in width and 300 metres in length within the following coordinates (WGS 84 Datum) from (E) to (H):

	<u>Latitude</u>	<u>Longitude</u>
(E)	22° 14.917'N	114° 02.029'E
(F)	22° 14.915'N	114° 02.031'E
(G)	22° 14.818'N	114° 01.891'E
(H)	22° 14.820'N	114° 01.889'E

The particulars of the lights for **Floating barrier 2** are as follows:

	<u>Latitude</u>	<u>Longitude</u>	<u>Characteristics</u>
(iii)	22° 14.819'N	114° 01.890'E	FL yellow 5s
(iv)	22° 14.852'N	114° 01.937'E	FL yellow 5s
(v)	22° 14.884'N	114° 01.983'E	FL yellow 5s
(vi)	22° 14.916'N	114° 02.030'E	FL yellow 5s

Floating barrier 3: Along the east-west direction with approximately 5 metres in width and 300 metres in length within the following coordinates (WGS 84 Datum) from (I) to (L):

	<u>Latitude</u>	<u>Longitude</u>
(I)	22° 14.848'N	114° 02.084'E
(J)	22° 14.846'N	114° 02.086'E
(K)	22° 14.749'N	114° 01.946'E
(L)	22° 14.751'N	114° 01.944'E

The particulars of the lights for **Floating barrier 3** are as follows:

	<u>Latitude</u>	<u>Longitude</u>	<u>Characteristics</u>
(vii)	22° 14.750'N	114° 01.945'E	FL yellow 5s
(viii)	22° 14.782'N	114° 01.992'E	FL yellow 5s
(ix)	22° 14.815'N	114° 02.039'E	FL yellow 5s
(x)	22° 14.847'N	114° 02.085'E	FL yellow 5s

2. Vessels navigating in the vicinity should proceed with caution and give a wide berth to the concrete pontoon floating barriers.

3. A drawing showing the positions of the floating barriers and the lights is attached to this Notice.

Ms Carol Yuen
Director of Marine

Marine Department


Government of the HKSAR

Date: 21 July 2023

Action File Ref.: L/M No. 29/23 in MD-PD&PS-F01-075-01A-001A-P049

海事處佈告第 125／2023 號附圖

Drawing Attached to Marine Department Notice No. 125/2023



不宜作航行用途

NOT TO BE USED FOR NAVIGATION