

Ships detained in Hong Kong by PSC Section in February 2011

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	7709394	OCEAN WIN	Panama	1978	1594	Container ship	Panama Bureau of Shipping	Panama Bureau of Shipping	Vision Shipping Limited	14/02/11	24/02/11	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for Master and officer/Master's national certificate of competence is not available on board, no flag endorsed certificate on board, one application for GMDSS operator endorsement from flag on board only, other (STCW)/no medical fitness certificate for all crew available on board; SAFETY OF NAVIGATION: echo-sounding device/echo sounder is not working, lights, shapes, sound-signals/air horn/whistle is not working, nautical publications/last notice to mariner on board is no. 16 2010 (22-Apr-2010), charts/all navigation charts were not updated (e.g. BA937, HK 1501, HK0801, HK0802, HK0803), nautical publications/tidal book NP204, radio signal book NP281(2), NP286(4), fog signal and light list NP79, chart catalogue NP131 not updated edition on board; MARPOL - ANNEX I: oil filtering equipment/oily water separator is not working, suspected discharge violation/two plastic hoses were arranged to pump engine room bilge water to sea; RADIOCOMMUNICATIONS: facilities for reception of marine safety information/navtex receiver is chinese language, all crew could not understand or operate, radio log (diary)/GMDSS log last entry was 13-Jan-2011, showed no test carried out for MF/HF.

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.