

## Ships detained in Hong Kong by PSC Section in November 2011

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	7129881	HUI SHENG	Sierra Leone	1971	660	General cargo/ multi-purpose ship	International Register of Shipping	International Register of Shipping	Vanguard Shipping Safety Management Consultant Co. Ltd.	09/11/11	14/11/11	FIRE SAFETY MEASURES: emergency fire pump, two fire hoses leaking during test of emergency fire pump test; MARPOL - ANNEX I: oil record book, C/E can not present oil record book, 15ppm alarm arrangements, crew (incl. C/E) can not test of 15ppm alarm of oily water separator; MARPOL - ANNEX V: garbage record book, master or c/o can not present garbage record book; STABILITY, STRUCTURE AND RELATED EQUIPMENT: stability/strength/loading information and instruments, stability booklet have no class proven stamp; CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: manning specified by the minimum safe manning document, engine rating crew one less than the requirement of minimum safe manning certificate
2	9251705	MSC FLORENTINA	Panama	2003	75590	Container ship	Germanischer Lloyd	Germanischer Lloyd; Registro Italiano Navale	Mediterranean Shipping Co Srl	28/11/11	28/11/11	SAFETY OF NAVIGATION: charts, no latest edition b.a. charts: 4119, 4121, 4122; FIRE SAFETY MEASURES: emergency fire pump, emergency fire pump not working; MARPOL RELATED OPERATIONAL DEFICIENCIES: oil and oily mixtures from machinery spaces, large volume of oily water in the bottom of aft e/r

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.