

Ships detained in Hong Kong by PSC Section in January 2012

| No. | IMO Number | Ship Name | Flag | YOB | GRT | Ship Type | Class | Related ROs | Ship Company | Date of Detention | Date of Release | Nature of Deficiencies (responsible RO, if any) |
|-----|------------|-----------|--------|------|------|----------------------------|---------------------------|---------------------------|-------------------------|-------------------|-----------------|---|
| 1 | 8223804 | HARVESTS | Panama | 1982 | 1238 | Refrigerated cargo carrier | Panama Bureau of Shipping | Panama Bureau of Shipping | Harvests Shipping Co SA | 05/01/12 | 11/01/12 | SHIP'S CERTIFICATES AND DOCUMENTS: minimum safe manning document, lack of one Engineer Officer as per MSMC; LIFESAVING APPLIANCES: rescue boat engine failed to start during inspection, other, three 2-way portable GMDSS radios not working; RADIOCOMMUNICATIONS: facilities for reception of marine safety information, NAVTEX, no received information found on board, facilities for reception of marine safety information, EGC system not working, last message received on 14.10.2011; ISM RELATED DEFICIENCIES: master's responsibility and authority, items no. 8, 9, 10, 12, 13, 14, 15 revealed the safety management system not properly implemented on board. |

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.