

## Ships detained in Hong Kong by PSC Section in June 2014

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	9371098	ASPIRATION	Panama	2005	12559	Container	Nippon Kaiji Kyokai	Nippon Kaiji Kyokai	Philsynergy Maritime Inc	03/06/14	04/06/14	FIRE SAFETY: personal equipment for fire safety/fire fighter's outfits in messy management, BA set and lifeline missing from stowage, safety lamps not approved type, air cylinders in use found zero or low pressure, jacketed high pressure lines and oil leakage alarm/main engine jacketed high pressure fuel leakage persistent alarm; LIFE SAVING APPLIANCES: launching arrangement for survival craft/stbd davit-launched liferaft, auto-release hook seized; ISM: emergency preparedness/officers and engineers failed to demonstrate emergency steering after 10 minutes waiting when requested
2	8891297	DOUBLE HAPPINESS I	Panama	1994	2752	Container	Overseas Marine Certification Services	Overseas Marine Certification Services	Hong Chuan International Logistics Co Ltd	11/06/14	- - -	FIRE SAFETY: fire detection and alarm system/fire control/detection system was turned off and showed alarm for captain deck when turned on; WATER/WEATHERTIGHT CONDITIONS: cargo & other hatchways/w/t/doors for cargo hold entrance hatch and mess room, fwd store hatch not closed properly for weather tight; POLLUTION PREVENTION - MARPOL ANNEX IV: sewage treatment plant/sewage treatment plant was turned off and not in use; POLLUTION PREVENTION - MARPOL ANNEX I: oil filtering equipment/oily water separator, unable to perform test by engineer; ISM: maintenance of the ship and equipment/poor maintenance of the ship during PSC inspections indicated the ISM verification not effectively implemented; SAFETY OF NAVIGATION: voyage or passage plan/passage plan not available for inspection
3	7927180	BORNEO AQUA NO. 2	Sierra Leone	1979	660	Other special activities	New United International Marine Services Ltd	New United International Marine Services Ltd; International Register of Shipping	Mark Ship Management & Consultant Co Ltd	13/06/14	20/06/14	SAFETY OF NAVIGATION: charts/previous and intended voyage charts BA1968, 3026, 4127, 937, 4121, 4119 not available, HK0801 not updated; POLLUTION PREVENTION - MARPOL ANNEX IV: sewage comminuting and disinfecting system/sewage treatment comminuter not operational; POLLUTION PREVENTION - MARPOL ANNEX I: oil filtering equipment/oily water filtering equipment not operational, oil and oily mixtures from machinery spaces/e/r tank top sludge accumulated about 40cm in depth

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.