

Ships Detained in Hong Kong Due to PSC Inspection in January 2017

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Classification society	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	8415873	XIANG SHENG	Sierra Leone	1984	1209	General cargo/ multipurpose	Union Bureau of Shipping	Union Bureau of Shipping	Xin Hong Tai Trading Ltd	03.01.2017	22.02.2017	<p>CERTIFICATE & DOCUMENTATION: NO ENDORSEMENTS BY FLAG STATE FOR ALL OFFICERS ON THEIR NATIONAL COC AND GMDSS CERTIFICATE WERE AVAILABLE., CERTIFICATE & DOCUMENTATION: SHORT OF 2 DECK RATINGS (STCW REG. II/4) AND 1 ENGINEER (STCW REG. III/1) AS PER MINIMUM SAFE MANNING CERTIFICATE, CERTIFICATE & DOCUMENTATION: NO CONTINUOUS SYNOPSIS RECORD ISSUED BY THE CURRENT FLAG STATE WAS AVAILABLE, SAFETY OF NAVIGATION: 1 OUT OF 2 9GHZ RADAR WAS MALFUNCTION WHICH WAS REQUIRED ON CARGO SHIP SAFETY CERTIFICATE, FIRE SAFETY: FIRE DETECTION AND ALARM SYSTEM WAS MALFUNCTION, POLLUTION PREVENTION: OIL FILTERING (15PPM) EQUIPMENT WAS RENDERED MALFUNCTION BY PUMP FAILURE., POLLUTION PREVENTION: SEWAGE TREATMENT PLANT WAS MALFUNCTION. SEWAGE WAS DIRECTLY OVERBOARD., FIRE SAFETY: E/R BLOWER FANS DAMPERS CANNOT BE CLOSED. E/R VENT MUSHROOM HEAD DEFORMED RENDERING INCAPABILITY OF CLOSING., RADIO COMMUNICATIONS: MF/HF DSC FAILED TO CONDUCT TEST, AND ERROR WAS SHOWN ON SCREEN., ISM: SMS NOT PROPERLY IMPLEMENTED AS EVIDENCED BY DEFICIENCY ITEM NO.4, 5, 6, 7, 8, 9, 13, 14, 15, 16, 21, 22, 23, 25, 26, 27, 29, 30, 31, 35, 37, 39..</p>

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.