

Ships Detained in Hong Kong Due to PSC Inspection in June 2017

No.	IMO No.	Ship Name	Flag	YOB	GRT	Ship Type	Classification Society	Related ROs	Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	9028639	FEI YUE 9	Mongolia	2004	2970	General cargo/ multi-purpose	Panama Maritime Documentation Services	Panama Maritime Documentation Services/ Foresight Ship Classification (FSCLASS)	Full Speed Marine Ltd	28.06.2017	08.07.2017	<p>RADIO COMMUNICATIONS: EPIRB ANNUAL TEST REPORT NOT AVAILABLE, CERTIFICATE & DOCUMENTATION: FIRE CONTROL PLAN, STABILITY BOOKLET AND DAMAGE CONTROL PLAN NO APPROVAL STAMP BY THE CLASSIFICATION SOCIETY LISTED ON CSR ITEM 11, SAFETY OF NAVIGATION: OBSOLETE PASSAGE ROUTES ON IN-USE NAUTICAL CHARTS CONFUSED WITH THE PASSAGE ROUTE OF LAST VOYAGE., SAFETY OF NAVIGATION: ECHO SOUNDER MALFUNCTION., FIRE SAFETY: SCBA (BOSUN STORE AND ACCOMMODATION) FOUND AIR LEAKAGE ON COUPLINGS BETWEEN AIR BOTTLE AND FACE MASK. NO LIFELINE WAS STOWED WITH FIREMAN OUTFIT AT BOSUN STORE, FIRE SAFETY: FIRE ALARM NOT AUDIBLE INSIDE E/R MACHINERY SPACE, ISM: SAFETY MANAGEMENT SYSTEM AS IMPLEMENTED ONBOARD DOES NOT ENSURE EFFECTIVE MAINTENANCE OF SHIP AS EVIDENCED BY DEFICIENCY ITEM NO. 4, 5, 6, 7, 8, 18, 19, 20, 24, 26, 27, 28, 29, 30, 32, 33, 34, 36, 37, 40, 42, 43, 44, 45, ISM: COMPANY DOES NOT ENSURE THAT CREWS ARE ABLE TO COMMUNICATE EFFECTIVELY AS EVIDENCED BY CHIEF ENGINEER WAS UNABLE TO COMMUNICATE WITH PSCO AND MASTER IN SHIP'S WORKING LANGUAGE.</p>