

Ships Detained in Hong Kong Due to PSC Inspection in June 2018

No.	IMO No.	Ship Name	Flag	YOB	GRT	Ship Type	Classification society	Related ROs	Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	9104512	BELLA J	Cyprus	1994	18997.00	Container ship	Nippon Kaiji Kyokai	Nippon Kaiji Kyokai; Russian Maritime Register of Shipping;	Victoria Oceanway Ltd	04.06.2018	05.06.2018	<p>POLLUTION PREVENTION: OILY WATER SEPARATOR BILGE PUMP IS NOT OPERATIONAL, CARGO OPERATIONS INCLUDING EQUIPMENT: MULTIPLE TWIST LOCK SOCKETS FOUND SEVERELY CORRODED, WASTED, DAMAGED AND CRACKED; POSING IMMEDIATE DANGER TO THE SECURING OF CARGO. RANDOM SAMPLING OF ACCESSIBLE SOCKETS ON BAY 2,6,10 AND 38 FOUND 12 DAMAGED SOCKETS., CARGO OPERATIONS INCLUDING EQUIPMENT: MULTIPLE HATCH COVER LOCKING CLEATS FOUND DAMAGED, SEIZED AND NOT OPERATIONAL. LOCKING CLEATS CAN NOT ENGAGE AND SECURE HATCH COVER PROPERLY. RANDOM SAMPLING OF ACCESSIBLE CLEATS FOUND 7 OUT OF 10 CLEATS WERE NOT IN PROPER ORDER., ISM: AS EVIDENCE OF DEFICIENCY NUMBER 15, SMS IN TERM OF SHIPBOARD OPERATIONS WAS NOT IMPLEMENTED EFFECTIVELY..</p>
2	8653047	CHANG DA 368	Belize	2007	5625.00	General cargo/multipurpose	Intermaritime Certification Services, ICS Class	Intermaritime Certification Services, ICS Class;	Sinounion Shipping Service Ltd	13.06.2018	19.06.2018	<p>FIRE SAFETY: 5 OUT OF 6 FIRE HOSES TESTED AND INSPECTED WERE DAMAGED/UNUSABLE. HOSE ON BRIDGE WING, 2ND DECK, 3RD DECK AND ENGINE ROOM WERE AFFECTED., POLLUTION PREVENTION: SEWAGE TREATMENT PLANT IS NOT OPERATIONAL, BLOWER AND SLUDGE PUMP NOT WORKING. VALVES OF SEWAGE SYSTEM WERE FOUND IN OVERBOARD DISCHARGE CONFIGURATION, FIRE SAFETY: HYPERMIST FIRE FIGHTING SYSTEM IS NOT OPERATIONAL, STAFF ARE UNFAMILIAR WITH OPERATION OF THE SYSTEM AND PUMP COULD NOT BE TURNED ON., ISM: VESSEL STAFF IS NOT ABLE TO ENSURE PROPER MAINTENANCE AND EMERGENCY PREPAREDNESS OF VESSEL.,</p>