Ships Detained in Hong Kong Due to PSC Inspection in November 2019

No.	IMO No.	Ship Name	Flag	YOB	GRT	Ship Type	Classification society	Related ROs	Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	8990172	YONG LI 16	Sierra Leone	2003	2268	Container Ship	Overseas Marine Certification Services		Fineway Marine Service Co Ltd	14.11.2019	27.11.2019	Echo sounder - THE ECHO SOUNDER IS MALFUNCTION Emergency fire pump and its pipes - THE EMERGENCY FIRE PUMP IS MALFUNCTION Auxiliary engine - THE NO.3 AND NO.4 GENERATORS ARE MALFUNCTION International shore-connection - THERE IS NO INTERNATIONAL SHORE CONNECTION ON BOARD Stability Information Booklet - THERE IS NO STABILITY BOOKLET ON BOARD SOPEP - THERE IS NO SOPEP BOOKLET ON BOARD Maintenance of the ship and equipment - 7. DEFICIENCIES FOUND DURING INSPECTION WERE OBJECTIVE EVIDENCES WHICH SHOWN THAT THERE WAS A FAILURE IN ENSURING THE VESSEL TO BE MAINTAINED EFFECTIVELY ACCORDING TO SMS AND ISM CODE