

Ships Detained in Hong Kong Due to PSC Inspection in January 2020

No.	IMO No.	Ship Name	Flag	YOB	GRT	Ship Type	Classification society	Related ROs	Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	8900517	CAROL HK	Panama	1990	43332	Bulk carrier	Bureau Veritas	Overseas Marine Certif	Fujian Marine Co Ltd	13.01.2020	17.01.2020	<p>Door - PORT SIDE WATERTIGHT DOOR OF ESCAPE TRUNK ON MAIN DECK TO TUNNEL WAS FOUND SEIZED, AND RUBBER GASKET STEEL CHANNEL DAMAGED SERIOUSLY</p> <p>Hull damage impairing seaworthiness - HULL SHELL PLATE LOCATED ON PORT SIDE NO.5 BALLAST TANK WAS FOUND DAMAGED AND BENT SERIOUSLY (ABOUT 1.5M X 1 M) AND TEMPORARILY REPAIRED. CLASS, FLAG AND PORT AUTHORITY WERE NOT INFORMED</p> <p>Fire-dampers - GALLEY VENT COVER ON LEVEL DECK 4(STARBOARD), TUNNEL VENT COVER ON MAIN DECK(P), ONE FUNNEL FLAP AND ONE E/R VENT DAMPER IN PORT SIDE FORWARD OF FUNNEL DECK WERE FOUND SEIZED</p> <p>Maintenance of the ship and equipment - DEFICIENCIES NO. 5 TO 13 WERE OBJECTIVE EVIDENCES WHICH SHOWN THAT THERE WAS A FAILURE IN ENSURING THE VESSEL TO BE MAINTAINED EFFECTIVELY ACCORDING TO SMS AND ISM CODE</p>