

Ships Detained in Hong Kong Due to PSC Inspection in April 2021

| No. | IMO No. | Ship Name | Flag | YOB | GRT | Ship Type | Classification society | Related ROs | Company | Date of Detention | Date of Release | Nature of Detainable Deficiencies (responsible RO, if any) |
|-----|---------|----------------|-------|------------|-------|----------------|------------------------|-------------|--------------------|-------------------|-----------------|--|
| 1 | 9255529 | SENTOSA TRADER | Malta | 15.05.2001 | 13764 | Container ship | LR | DNVGL (ISM) | Lomar Shipping Ltd | 15.04.2021 | 17.04.2021 | <ol style="list-style-type: none"> 1. Free fall type Lifeboat could not be started by No.2 battery; 2. Self-closing device for fire door of air conditioning room in accommodation was found dismantled and the door was lashed open by rope; and 3. After reviewing the oil spill case of fuel oil and interview with Master, Chief engineer and Duty engineer, there was not always evidence indicated that the key shipboard operation concerning protection of environment was followed properly. |