

Ships Detained in Hong Kong Due to PSC Inspection in June 2021

No.	IMO No.	Ship Name	Flag	YOB	GRT	Ship Type	Classification society	Related ROs	Company	Date of Detention	Date of Release	Nature of Detainable Deficiencies (responsible RO, if any)
1	9524360	LIMCO MARU	Vietnam	10.04.2007	2363	General Cargo Ship	VR	VR	TRUONG MINH SHIPPING CO LTD	15.06.2021	18.06.2021	<ol style="list-style-type: none"> 1. Dirty oil sludge tank discharge pipe wasted and the connection flange damaged into two sections; 2. Diesel oil tank (P) and Aft station hydraulic oil tank vent pipes damaged and broken into two sections; 3. No. 1 Ballast water tank (P) and No.3 Ballast water tank (S) vent heads were found internal floating valve missing; 4. Forecastle store room and Paint locker vent heads can't be closed by ship crew; 5. Two of no.2 cargo hold (Fwd) ventilation pipe covers can't be closed up during PSCO inspection; 6. Missing of connection flange coupling on fire hydrant at main deck (P), missing of fire nozzles at main deck (P&S) and damaged of fire hose of connection at main deck (P) were found during PSCO inspection; and 7. The deficiencies in the PSC inspection report indicated that the SMS implemented onboard failed to ensure the ship's effective maintenance.