

Ships Detained in Hong Kong Due to PSC Inspection in August 2021

No.	IMO No.	Ship Name	Flag	YOB	GRT	Ship Type	Classification society	Related ROs	Company	Date of Detention	Date of Release	Nature of Detainable Deficiencies (responsible RO, if any)
1	8891297	SF BLOOM	Palau	02/04/1994	2752	General Cargo/Multipurpose	International Register of Shipping	International Register of Shipping	Sino Ever Treasure Limited	22/08/2021	24/09/2021	<p>1. Fire control panel onboard bridge was found a lot of alarms and shipboard personnel cannot demonstration of fire alarm testing to PSCO;</p> <p>2. Lifeboat engine could not be demonstration of starting during PSCO inspection;</p> <p>3. Emergency fire pump could not be demonstration to PSCO; and</p> <p>4. The entire deficiency items in the PSC inspection report indicated that the SMS implemented onboard failed to ensure the ship's effective maintenance.</p>