

Ships Detained in Hong Kong Due to PSC Inspection in July 2022

No.	IMO No.	Ship Name	Flag	Date of Keel Laid	GRT	Ship Type	Classification society	Related ROs	Company	Date of Detention	Date of Release	Nature of Detainable Deficiencies (responsible RO, if any)
1	9237187	PACIFIC 07	Panama	06.06.2002	29862	Bulk Carrier	American Bureau of Shipping (ABS)	American Bureau of Shipping (ABS) ; Overseas Marine Certification Services (OMCS)	International Transportation & Trading JSC	25.07.2022	04.08.2022	<ol style="list-style-type: none"> 1. Lighting and exhaust fan do not work in the hospital toilet, the general lighting in hospital is inadequate for the area. 2. The fire nozzles and its hoses are not readily to be used on deck. The entire fire hose boxes can't be found the fire-fighting apparatus on main deck. 3. Forward main fire pipe was found leakage seriously, and there is temporarily clamped by a large hose clamp.