

Ships Detained in Hong Kong Due to PSC Inspection in April 2023

No.	IMO No.	Ship Name	Flag	Date of Keel Laid	GRT	Ship Type	Classification society	Related ROs	Company	Date of Detention	Date of Release	Nature of Detainable Deficiencies (responsible RO, if any)
1	9370599	GUO XING 2	Belize	18.12.2004	1989	General cargo/Multipurpose	Intermaritime Certification Services	Intermaritime Certification Services	B.O.W SHIPPING CO., LIMITED	06.04.2023	12.04.2023	1. Emergency fire pump was found insufficient pressure (max. 2 bar) and insufficient pressure at aft fire hose when the time of inspection; and 2. Oil accumulation was found under main engine and auxiliary engine. The depth of oily water was over 200mm on the tank top in engine room.
2	9958078	SKY TIARA	Panama	25.12.2020	9940	Container ship	Nippon Kaiji Kyokai	Nippon Kaiji Kyokai	DY SMC CO., LTD.	13.04.2023	14.04.2023	1. Demonstration of the Oily Water Separator 15ppm alarm test failed; and 2. Rescue boat engine was inoperative.