

Ships Detained in Hong Kong Due to PSC Inspection in May 2025

No.	IMO No.	Ship Name	Flag	Date of Keel Laid	GRT	Ship Type	Classification society	Related ROs	Company	Date of Detention	Date of Release	Nature of Detainable Deficiencies (responsible RO, if any)
1	1099773	TPT PIONEER	Mongolia	01.02.1979□	330	Tug	JI TAI MARITIME PTE LTD		TPT Marine Sdn Bhd	15.05.2025	20.05.2025	1.Shore-based maintenance certificate required by the International Safety Radio Certificate was not available. 2.MF/HF radio equipment was missing according to the record of equipment for Cargo Ship Safety Radio (Form R). 3.The Chief Engineer and Second Engineer lack flag state endorsements, and one qualified engine rating position required by the Minimum Safe Manning certificate is vacant. 4. The stern anchor light was not functioning. 5.The manual fire pump was inoperative.