No.: 21/2012

Telephone No. : (852) 2852 3001 Fax No. : (852) 2544 9241 Telex No. : 64553 MARHQ HX

E-mail: hkmpd@mardep.gov.hk Web site: http://www.mardep.gov.hk



香 港 商 船 資 訊

HONG KONG MERCHANT SHIPPING INFORMATION NOTE


Unified Interpretations of the 1966 Load Lines Convention and the 1988 Load Lines Protocol as modified by resolution MSC.143(77) relating to the regulation 25(2) and (3) for protection of the crew

To: Shipowners, Ship Managers, Ship Operators, Ship Masters, Classification Societies and Shipbuilders

Summary

The purpose of this Note is to promulgate the unified interpretations of the 1966 Load Lines Convention and the 1988 Load Lines Protocol as modified by resolution MSC.143(77) relating to the regulation 25(2) and (3) for protection of the crew.

- 1. The Maritime Safety Committee of the International Maritime Organization (IMO), at its 90th session in May 2012, approved a circular LL.3/Circ.208 on unified interpretations of the 1966 Load Lines Convention and the 1988 Load Lines Protocol as modified by resolution MSC.143(77) relating to the regulation 25(2) and (3) for protection of the crew, with a view to providing more specific guidance for the application of requirements concerning guard rails.
- 2. The unified interpretations should be used as guidance when applying relevant provisions of the 1966 Load Lines Convention and the 1988 Load Lines Protocol as modified by resolution MSC.143(77), on or after 22 May 2012.
- 3. The IMO circular LL.3/Circ.208 as an attachment to this Note can be found on the webpage of Marine Department (http://www.mardep.gov.hk/en/msnote/msin.html).



Marine Department Multi-lateral Policy Division

27 June 2012