No.: 41/2012

Telephone No.: (852) 2852 3001

Fax No. : (852) 2544 9241 Telex No. : 64553 MARHQ HX

E-mail: hkmpd@mardep.gov.hk Web site: http://www.mardep.gov.hk



## 香港商船資訊

## HONG KONG MERCHANT SHIPPING INFORMATION NOTE

## **Pilot Transfer Arrangements – Revision of Poster**

To: Shipowners, Ship Managers, Ship Operators, Ship Master and Officers

## **Summary**

This Note advises parties concerned of the revision of a poster depicting the required boarding arrangements for pilot.

- 1. The Maritime Safety Committee of the IMO, at its 90<sup>th</sup> session in May 2012, approved a revision of the poster depicting the required boarding arrangements for pilots. The revised poster incorporates the most significant changes in the above arrangements by previous adoption of the resolutions MSC.308(88) i.e. amendments to the Required Boarding Arrangements for Pilots in December 2010 and A.1045(27) i.e. Pilot Transfer Arrangements in November 2011.
- 2. The circular MSC.1/Circ.1428 can be found on the webpage of Marine Department (http://www.mardep.gov.hk/en/msnote/msin.html) as an attachment to this Note.
- 3. Shipowners, ship managers, ship operators, ship masters and officers are advised to replace the previous poster with the revised poster on board their vessels.

Marine Department Multi-lateral Policy Division

18 July 2012